## District I 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 882 1000 Rio Brazos Road, Aztec, NM 874 District IV 1220 S. St. Francis Dr , Santa Fe, NM 875

\* Attach Additional Sheets If Necessary

## State of New Mexico Energy Minerals and Natural Resources

**OCD-ARTESIA** 

Revised March 17, 1999

Form C-141

side of form

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

AUG 13 2007 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back

Release Notification and Corrective Action													
		34749		<b>OPERA</b>			Initi	al Report	$\boxtimes$	Final Repor			
Name of Company BTA Oil Producers						Contact ☐ Pam Inskeep							
Address 104 S. Pecos, Midland, TX 79701 Facility Name Owl, 20504 JV-P, #1						Telephone No. ☐ (432) 682-3753  Facility Type ☐ Well							
Facility Name Owl, 20504 JV-P, #1													
Surface Ow	nerForeha	ind Ranch/gr	)wner	Federal Lease No.□ NMNM 114969						14969			
				LOCA	ATIO	N OF REI	LEASE						
				North/ South	South Line	Feet from the 2130	East/V East	West Line   County □ Eddy					
,	NATURE OF RELEASE												
Type of Rele		Minor	. 1		Volume of Release       20-30 bbls       Volume Recovered□       20 bbls est         Date and Hour of Occurrence       Date and Hour of Discovery□								
Source of Release Tank leak, undermined cause at this time						am CDT, 5		Date and Hour of Discovery ☐ 12 pm CDT, 5/10/2007					
Was Immediate Notice Given?  As soon as notified in the office ⊠ Yes □ No □ Not Required						If YES, To Whom?							
By Whom? □ Pam Inskeep						Date and Hour□ 2:50 pm CDT 5/10/2007							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If a Watercou	irse was Im	pacted, Descr	ibe Fully.*	k									
N/A													
IN.	/A												
Describe Cause of Problem and Remedial Action Taken.*													
The estimated release was contained within the dike area. The area inside the dike is lined. There was a good amount of rainwater standing inside the dike, as there was a large volume of rain in the area for the three days prior to the release. A vacuum truck was called in and removed all fluid possible. No produced oil was recovered. The contaminated gravel (floor inside the dike) was removed by Dansur LLC. and the liner was washed with a hot oiler. E.D. Walton Construction Co., Inc. disposed of the gravel at Controlled Recovery, Inc. Clean gravel was brought in and spread. No further remediation is anticipated.													
Describe Are	a Affected	and Cleanup A	Action Tak	ten.*				,					
See a	oove explai	nation											
regulations al public health should their cor the environ	I operators or the envi operations h nment. In a	are required to ronment. The lave failed to a	report an acceptanc dequately CD accep	nd/or file certain rece of a C-141 reportance and received and receive	elease no ort by the emediate	otifications ar NMOCD ma contamination	knowledge and und perform correct arked as "Final Reson that pose a threet the operator of resources.	tive acti eport" d eat to gr	ons for rele oes not reli ound water	eases which eve the open s, surface wa	may en rator of ater, hur	ndanger Thability man health	
Signature:	Hyn	, Ih	ON V		OIL CONSERVATION DIVISION								
Printed Name	: I	am Inskeep	1	4	Approved by [	District Supervis	sor:	Ja	ng	<del>)</del> ~	y		
Title:		Regulatory Adı	Approval Date: 2007 Expiration Date:										
Date 8/0	09/2007		Phon	e: (432) 682-375	3	Conditions of	Approval:			Attached			