Form 3160-5 (February 20

OCD-ARTESIA **UNITED STATES**

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

use this form for proposals to drill or to re-enter an

	FORM APPROVED			
	OMB No 1004-0137			
	Expires March 31, 2007			
âse Seri	al No			

5. Leâse Serial No NM-NM100540

6 If Indian, Allottee or Tribe Name

aoandoned well.	Use Form 3160-3 (A	PD) for such propos	ais.	<u> </u>	
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No	
1. Type of Well Oil Well Gas V 2. Name of Operator Devon Energy Production Co., LP 3a Address 20 North Broadway OKC, OK 73102 4 Location of Well (Footage, Sec., T., SL 660: FSL & 1910: FEL Sec 18-1228-R26E		3b Phone No (include area (405)-552-7802		8. Well Name and No. Filaree 18 Federal 1 9. API Well No 30-015-31707 10. Field and Pool or E WC McGruder; Wolfe 11. Country or Parish, S	camp Gas
BHL 1935' FSL & 712' FE. Sec 18-T22S-R26E	E Lot I			Eddý County, NM	
12 CHEC	K THE APPROPRIATE BO	X(ES) TO INDICATE NATU			ER DATA
TYPE OF SUBMISSION	E OF SUBMISSION TYPE OF ACT				
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat		uction (Start/Resume) amation	Water Shut-Off Well Integrity
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon		omplete porarily Abandon	Other Plugback to Wolfcamp from Morrow
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Wate	r Disposal	
13 Describe Proposed or Completed O the proposal is to deepen direction. Attach the Bond under which the v following completion of the involv testing has been completed. Final determined that the site is ready for	ally or recomplete horizontall work will be performed or proved operations. If the operations Abandonment Notices must be	ly, give subsurface locations a wide the Bond No. on file with on results in a multiple complete.	nd measured an h BLM/BIA. R etion or recomp	nd true vertical depths of Lequired subsequent repo letion in a new interval,	f all pertinent markers and zones orts must be filed within 30 days a Form 3160-4 must be filed once
04/18/07 - 05/01/2007:					
MIRU. Bled csg & tbg all gas - NU/11,395'. RIH perf Wolfcamp @ 928 NU/TREE. Swab. MIRU tree saver, tbg - rls pkr. Bled dwn well all gas - NU Tree. Swab. Acidize Wolfcamp 9237'. RD swab. Put well on production.	4-9290; 9301-9311; 9393- , tstd lines to 9500 psi. RU · TOH w/tbg & pkr. RIH & ; @ 9284′ - 9414′ dwn tbg w	9414'; (4SPF) 148 holes. R pmp trk to monitor back sic set CIBP @ 11,240' + 35' c	RD W/L, RIH w de. Pmp 5000 mt on top. Ne	//5.5" pkr & tbg. Set pk) gals acid. Swab. RD ew PBTD @ 11,205'. S	kr @ 9223', NU/DN/BOP - swab - NU/DN/Tree NU BOP, Ld Set pkr @ 9237', NU/DN/BOP -
See Form 3160-4 for all other pertin	ent recompletion informati	on. ·			
14 I hereby certify that the foregoing is t	rue and correct				

Stephanie A. Ysasaga Title Sr. Staff Engineering Technician Date 06/13/2007 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE ACCEPTED Approved by Title Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office entitle the applicant to conduct operations thereon. Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of life-United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)