## Form 3160-5 UNITEDSTATES DEPARTMENT OF THE INTERIOR OCD-ARTESIA April2004) BUREAU OF LAND MANAGEMENT

FORMAPPROVED OM B No. 1004-0137 Expires: March 31, 2007

١	<ol><li>Lease Serial No</li></ol>
l	5. Lease Serial No NMNM2918

SUNDKI	MOTICES	AND	KEPUKIS	OIN	VVELLS
not use th	is form for	propos	als to drill	or to	re-enter an

abandoned well. Use Form 3160 - 3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name


-								
SUBMIT IN TRI	PLICATE - Other ins	7. If Unit or CA/Agreement, Name and/or No NMNM71016X						
1. Type of Well    X   Oil Well					8. Well Name and No.			
2. NameofOperator BEPCO, L.P.		GOLDEN LANE "17" FEDERAL #2Y  9. API Well No						
3a. Address P.O. BOX 2760 MIDLANI	O TX 79702-2760	e area code) 77	30-015-35712 10 Field and Pool, or Exploratory Area					
4. Location of Well (Footage, Sec	., T., R., M., or Survey Descr		_	GOLDEN LANE, SOUTH (DELAWARI				
775' FNL, 330' FEL, SEC. 17, T21S, R29E SEP 0 4 2007					11. County or Parish, State EDDY			
		OCD-ARTI	ESIA	NM				
12. CHECK AF	PPROPRIATE BOX(ES)T	O INDICATE NATUR	E OF NOTICE, R	EPORT, OR	OTHER DATA			
TYPE OF SUBMISSION		TYI	PEOF ACTION					
<ul><li></li></ul>	Acidize AlterCasing Casing Repair Change Plans Convert to Injection	Deepen FractureTreat New Construction Plug and Abandon Plug Back	Production (State Reclamation Recomplete Temporarily Ab	[] [] pandon	Water Shut-Off Well Integrity X OtherCommingling, offlease stor. & measurement			
Attach the Bond under which t following completion of the in-	ectionally or recomplete horizon the work will be performed or provolved operations. If the operational Abandonment Notices shall by for final inspection.)	ntally, give subsurface location rovide the Bond No. on file on results in a multiple com be filed only after all require	ons and measured and t with BLM/BIA. Requipletion or recompletion ements, including reclar	rue vertical depti ired subsequent in a new interva nation, have bee	hs of all pertinent markers and reports shall be filed within 30 il, a Form 3160-4 shall be filed on completed, and the operator l	zones. days once has		
Lane "17" Federal #2Y.								


request for off-lease storage and measurement will allow for more efficient operations with a Consolidated Battery by reducing the number of stock tanks and water tanks. Using the existing facility will also minimize surface disturbance: Full wellstream production will be transported via flowline to a three phase heater treater where oil, water and gas will be separated at this vessel. The oil and water will be metered prior to being stored in commingled stock tanks and water tank. The gas will be metered via a separate allocation meter.

## SEE ATTACHED FOR CONDITIONS OF APPROVAL

		1		LES BABYAK
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)			j	PETROLEUM ENGINEER
ANN MOORE	Title	PRODUCTION	I CLERK	
Signature amore	Date	08/20/2007		
THIS SPACE FOR FEDERA	LOR	STATE OFFICE	USE	
Approved by		Title		Date
Conditions of approval, if any, are attached. Approval of this notice does not wa certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.		Office		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for	any person	n knowingly and willfull	y to make to	any department or agency of the United

States any false, fictitious or fraudulent statements or représentations as to any matter within its jurisdiction.





VALVE SEALING DETAIL					= Production Li	ne BEPCO, L.P.
Phase		SV1	SV2	SV3	= Oil Dump Line	Golden 8 Battery
Produc	ction	Sealed	Sealed	Open	= Gas Line	Sec 8, T21S, R29E
Recycl	e	Sealed	Open	Sealed	= Water Line	Well #'s 1, 2, 4
Sales		Open	Sealed	Sealed	Test Line (Oil)	Golden D Battery
		•			= Circulating Li	ne Sec. 8, T21S, R29E
						Well #'s 2, 3, 4
⊗	⊗ ≈ Sealed Valve				Golden SWD	Golden B Battery
0	⊕ = Valve				Golden 8 # 3	Sec. 8, T21S, R29E
ww	ww = Water Meter				Golden D # 1	Well#1
ом	ow ≕ OilMeter					Golden Lane 17 Bty.
3 P HT	= 3 P	hase Heater	•			Sec 8, T21S, R29E
3 P Test	= 3 P	hase Sep.				Well # 1, 2Y
2 P Sep	= 2 P	hase Sep.				
2 P GS	2 P GS = 2 Phase Gas Scrubber					1
3 P T HT	= 3 P	hase Test H	eater Treat	er	WHF 9/28/2006	

ä