Form 3160 5 ebruary 2005 UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

OCD-ARTESIA

FORM APROVED

OMB NO. 1004-0135 EXPIRES: March 31, 2007 5. Lease Serial No.

pornot use this form for proposals to drill or to re-enter an				6. It Indian, Allottee of	NM 89051
abandoned well. Use Form 3160-3 (APD) for such proposals				o. Il Indian, Allottee t	of Tilbe Name
SUBMIT IN TRIPLICATE 1a. Type of Well Oil Well Gas Well Other			7. Unit or CA Agreement Name and No.		
				7. Shill of SATIgreement Hame and 146.	
				8 Well Name and No.	
2. Name of Operator				Apache 13 Federal 1	
2. Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP SEP 2 0 2007				9. API Well No.	
3. Address and Telephone.No. OCD-ARTESIA				30-015-27434	
20 North Broadway, Oklahoma City, OK 73102 405-235-3611			•	10 Field and Pool, or Exploratory	
4. Location of Well (Report location clearly and in accordance with Federal requirements)* 1330' FNL 330' FEL SEC 13 T22S R30E				Los Medanos;Strawn	
				11. County or Parist	n State
			Eddy	NM	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OS SUBMISSION		TYPE	OF ACTION		_
☐ Notice of Intent	Acidize	Deepen		n (Start/Resume)	Water Shut-Off
☐ Alter Casing ☐ Fracture Treat ☐ Reclar ☐ Subsequent Report ☐ Casing Repair ☐ New Construction ☐ Recom				<u></u>	
l <u> </u>	Change Plans	Plug and Abandon		ily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dis	-	
13 Describe Proposed or Completed Operations (C					
deepen directionally or recomplete horizontally, give so the Bond No on file with BLM/BIA Required subsequi-					
interval, a Form 3160-4 shall be filed once testing has determined that the site is ready for final inspection)	been completed Final Abandonment N	lotices shall be filed only after all req	uirement, including	reclamation, have been cor	mpleted, and the operator has
MIRU PU. ND TREE. NU BOP. tbg 12,428-38' & 12,549-54' @ 2 Flush w/ KCL wtr. RU PT & LT w Strawn w/ 2500 gals 15% NEFE ND WH & NU BOP. Pump 8 bbls perfs w/ 2500 gals HCL acid w/ 2	spf: 48 total holes. No f w/ 55 bbls KCL wtr. No fl w/ 75 BS. Flush w/ KCL s KCL wtr dn tbg. RU sv	flow or vac on tbg after low or vac on tbg. SW . wtr. RU & RIH w/ sw vivel & pull pkr. Little o	perf. Swa /I. RU & RI ab. Left on gas flow. R	b tbg. Acidize w/ H w/ swab. RU E 16/64" choke. R U & RIH w/ swab	500 gals 15% NEFE. BJ Services & acidize U slick line. SWI. Acidize Strawn
14. I hereby certify that the foregoing is to	rue and correct				
	Name				
Signed freely	Title	Regulatory Ana	ılyst	Date	9/13/2007
(This space for Rederal or State Office us	刺FCORD				
Approved by	R GIASE			Date	
Conditions of approval, if tarty	T. WHAVE				*****
SEP 18 2	007				
Title 18 0 3 C Section 1001, makes it a crime for any	person knowingry and wimuny to make a		eu States any raise	s, noncous or maddulent state	ements or representations to any matter
	100	within its jurisdiction			
DAVID R. GL	∧oo *See	Instruction on Reverse S	ıue		

PETROLEUM ENGINEER