Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD-ARTESIA	6	OC.	D-A	R.	Œ	SIŽ	À
-------------	---	-----	-----	----	---	-----	---

OM B No 1004-01 Expires: March 31	37
5. Lease Serial No.	



	LC-050158
6.	If Indian, Allottee or Tribe Name

SUNDRY	NOTICES AND RE	EPORTS ON WE	LLS	LC-050	158
Do not use the abandoned w	nis form for proposals ell. Use Form 3160 - 3	to drill or to re-e (APD) for such pro	enter an Oposals.	6. If Indian.	, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. NM 109695X	
1. Type of Well Oil Well □ □	Gas Well C Other			8. Well Nan	
2. Name of Operator Fairway Res	ources Operating, LLC			South R 9. API We	led Lake II Unit #14 Il No.
3a. Address 538 Silicon Drive, Suite 101, So	3b. Phone No. (include 817/416-1946	3b. Phone No. (include area code) 817/416-1946		30-015-05596 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T. R., M., or Survey Description) NOV 0 6 2007				Redlake, QN, GB, SA	
2,080' FNL and 560' FEL, Section 35-T17S-R27E				11. County or Parish, State	
		OCD	-ARTESIA	Eddy C	ounty, NM
12. CHECK AI	PPROPRIATE BOX(ES) TO	O INDICATE NATUR	E OF NOTICE, RI	EPORT, OR	OTHER DATA
TYPE OF SUBMISSION		TYP	E OF ACTION		
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (State Reclamation Recomplete Temporarily Abs	·	Water Shut-Off Well Integrity Other
	ectionally or recomplete horizonta	ally, give subsurface location	is and measured and true	vertical depth	rk and approximate duration thereof s of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

9/18/07 - RIH w/tbg. to 1,520'. circulated hole w/mud laiden fluid. Spot 25 sx cement @ 1,520'. WOC 4 hrs. BLM said too soft. SDFN 9/19/07 - Tagged plug @ 1,255!. POH to 700'. Spot 25 sx cement plug. WOC 4 hrs. Tagged soft cement again. Pulled up to 700'. Spot 10 sx cement plug. POH w/ tbg. SDFN.

9/20/07 - Tagged plug @450'. ND BOP. RIH to 60'. Circulated 20 sx cement to surface. Cut off well head and weld on dry hole marker. Rigged down.

Accepted for record

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)					
Cindy Flood	Title	Office Manager			
Signature Cemelia Walant	Date	10/26/2007			
OR FEDERAL OR STATE OFFICE USE					
Approved by /S/DAVID R. G. of this r	ASS	PETROLEUM ENGINEER	Date NOV 0 1 2007		
	ights in the subject lease	Office	A Section 1		
Title 18 U States any	crime for any person as to any matter within	knowingly and willfully to make to a its jurisdiction.	iny department or agency of the United		