

Submit 3 Copies To Appropriate  
District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised June 10, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



WELL API NO. 30 015 10538
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State 647 AC 731
8. Well Number 204
9. OGRID Number 184860
10. Pool name or Wildcat. Artesia, Queen-Grayburg-San Andres

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other (Injection) ☐

2. Name of Operator  
Melrose Operating Company

3. Address of Operator  
c/o P.O. Box 953, Midland, TX 79702

4. Well Location (Surface)

Unit Letter B : \_\_\_\_\_ feet from the North line and \_\_\_\_\_ feet from the West line

Section 33 Township 18S Range 28E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.):

12 Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10-28-07: Nipped up wellhead, TIH w/pump & rods. Hang well on, tagging good pump action.

10-31-07: Roustabout crew, dug 2 ft. around wellhead, inspecting 4 1/2" & 7" casing. TOH w/pump & rods. RIH & set RBP @ 1350'.

11-1-07: Load 4 1/2" casing w/water, load 7" casing w/water. Weld new collar & wellhead on 7". Welder made 4 1/2" casing cutoff removing 4' of bad casing. Weld slip to slip collar weld new casing stub & slip to thread collar. Installed Larkin K wellhead 4 1/2" to 2 3/8". Installed wellhead connections to 7" casing bowl to surface & installed wellhead connections to 4 1/2" casing. Backhoe backfill around casing. Nipple up wellhead, TIH w/pump & rods.

11-2-07: Hung well on, good pump action, rigged down.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Regulatory Agent DATE: 11-5-07

Type or print name Ann E. Ritchie E-mail address: ann.ritchie@wtor.net Telephone No. 432 684-6381

(This space for State use)

APPROVED BY Runeo INAB TITLE Compliance Officer DATE 11/13/2007

Conditions of approval, if any: