BLM

Form 3160-5 (February 2005)		UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OPERATOR'S COPY		COPY	FORM APROVED OMB NO, 1004-0137 EXPIRES March 31, 2007		
8UNDRY NOTICES AND REPORTS ON WELLS					5. Lease Serial No		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals					NW 6. It Indian, Allottee o	ILC049648A	
SUBMIT IN TRIPLICATE - Other instructions on page 2						A Prise Hallo	
1. Type of Well					7. Unit or CA Agreement Name and No.		
☑ Oil Well ☐ Gas Well ☐ Other					8 Well Name and No.		
2. Name of Operator					Julia A Federal 5		
DEVON ENERGY PRODUCTION COMPANY, LP					9. API Well No.		
3a, Address	a deno. Oblahama Oliv. Ole 22400	3b. Phone No. (include area code)			30-015-30048		
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-46 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					10. Field and Pool, or Exploratory Area Red Lake; Q-GB-\$A		
1650 FNL 530 FVVL 5 T18\$ R27E					11. County or Parish, State		
					Eddy NM		
12. CHECK APPROPRIATE BOX(98) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OS SUBN				OF ACTION			
Notice of Intent	│	Ļ	_ Deepen ☐ Fracture Treat	Production Reclamate	on (Start/Resume)	☐ Water \$hut-Off ☐ Well Integrity	
Subsequent Repo	ort Casing Repair	<u></u>	New Construction	Recomple		Other	
☐ Final Abandonmo	ent Notice Change Plans	_	Plug and Abandon		rily Abandon		
13 Operatibe Proposed or Cor	Convert to Inje		Plug Back nent dates, including estimated o	Water Di		note duration thereof if the proposal	
deepen directionally or recomple	ete horizontally, givo subsurface location and messur	od and true ver	tical depths of all perlinent mark	ers and zones, A	Attach the Bond under which th	ia work will be performed or provide	
the Bond No, on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operation: If the operation results in a multiple completion or recompletion in a new interval, a Form 3180-4 shall be filed once testing has been completed, and the operator has determined that the site is ready for finel inspection)							
decommend that with wife to leady	TO HER POSPOSION						
	n 12/14/07. o 1,554'. Test casing to 500 psi. x cement from 1,554' to 960' in 5					d to tag per	
1					ACCEPTED	TOD DECODD	
5. Cut wellhead off 3' below ground level. Set dry hole marker.					HUUEPIED	FOR RECORD	
6. Cleaned location]			
7. Plugged & Abandoned - 1/8/08					1	1 1	
JAN					JAN :	1 6 2008	
Accepted for record							
MICCO PT							
BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE						ND MANAGEMENT	
				L	CARLSDAD	LIELU OFFICE	
14. I hereby certify that to Name: Ronnie Stat	ne foregoing is true and correct	Title	Engineering Techn	Irlan			
Da. Mak			1/4/20	TOPATI			
Signature Roman Mack Date 1/8/08							
	THIS SPACE	FOR FEE	DERAL OR STATE	OFFICE L	JSE		
Approved by							
		Title			Date		
Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct or operations thereon. Office							
	entitle the applicant to conduct or operations thereon. Office Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any take, notitious or induduiont statements or representations as to any matter within its jurisdiction.						
representations as to any matter v	within its judadiction	Selective trooping	ny esta wilindily to moko to arty da	hertwent or ago	ncy of the United States any ta	ice, notitious or fraudujont stetements or	

(Instructions on page 2)

DEVON ENERGY PRODUCTION COMPANY LP Well Name: JULIA A FEDERAL #5 Field: RED LAKE Location: 1650' FNL & 530' FWL; SEC 5-T185-R27E County: EDDY State: NM Elevation: 3453' KB: 3444' GL Spud Date: 5/7/98 Compl Date: 5/23/98 API#: 30-015-30048 Prepared by: Ronnie Slack Date: 1/8/08 Rev: Plug & Abandonment 1. Spot 25 Sx cement from 247' to surface. PLUGGED & ABANDONED 2. Cut wellhead off 3' below ground level 3. Set dry hole marker. Cleaned location. 1/8/08 10# Mud Plug & Abandonment 1. TIH w/tubing to 1,554'. Test casing to 500 psi. Ok. 2. Circulate hole w/10# salt gel mud. 3. Circulate 60 Sx cement from 1,554' to 960'. Not 12-1/4" Hole required to tag TOC per BLM. 8-5/8", 24#, J55, @ 1,157' Cmt'd w/550 Sx. Circulated to surface CIBP @ 1554" (8/11/04) SAN ANDRES 1600' - 1690' 1807' - 1898' 1905' - 1926' 7-7/8" Hole 2350' PBTD 5-1/2", 15.5#, J55, @ 2,392' Cmt'd w/500 Sx. Circulated to surface. 2395' TD