Form C-103 State of New Mexico Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-015-30869 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE 😠 FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S St Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A SOUTH BOYD 27 DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well X Gas Well Other 9. OGRID Number 2. Name of Operator OCD-ARTESIA 015742 NEARBURG PRODUCING COMPANY 3. Address of Operator 10. Pool name or Wildcat North Seven Rivers; Glorietta/Yeso 3300 N. A St. bldg. 2, Ste 120, Midland, TX 79705 4. Well Location 2310 feet from the ____ 990 Unit Letter line and feet from the line Township 19 S Range 25 E **NMPM** County EDDY 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,4391 Pit or Below-grade Tank Application or Closure Pit type _____ Depth to Groundwater ___ __ Distance from nearest fresh water well _____ Distance from nearest surface water ___ Pit Liner Thickness: . Below-Grade Tank: Volume ____ _bbls: Construction Material _ 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. [**PLUG AND ABANDONMENT** CASING TEST AND **PULL OR ALTER CASING MULTIPLE** COMPLETION CEMENT JOB OTHER: OTHER: PLUG BACK 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1-11-08 Notify CCD. 1-14-08 Set CIBP @6,650'. Perf. @6,648'. Set CR @6,615'. 1-15-08 Spot 10# M.L.F. @ 6,615'-3,600'. Sqz. 40 sx. cmt. under CR @6,615' thru perfs. @6,648'w/communication out 7 X 9 5/8 annulus. Spot 18 sx. cmt. 6,615'-6,508'. 1-16-08 Set CIBP @3,750'. 1-17-08 Cut & pull 7" csg. from 3,740'. 1-18-08 Run 7" csg. to 2,920'. 1-21-08 Spot 40 sx. cmt. 3,750'-3,631'. Spot 35 sx. cmt. 3,150'-3,056'. Set CR @2,894'. Pump 457 sx. cmt. under CR w/cmt. Circulate to surface out 7" X 9 5/8" csg. Unstring from CR. Spot 10 sx. cmt. 2,894'- 2,835'. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines _____, a general permit ____or an (attached) alternative OCD-approved plan ____ P & A SUPV. ____ DATE _____1-12-08 2 TITLE_ SIGNATURE. E-mail address: Type or print name RANDALL MINEAR Telephone No. (432) 530-0907 For State Use Only

__ TITLE_

_____ DATE _

APPROVED BY

Conditions of Approval, if any: