

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

S

WELL API NO.  
30-005-62798

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
LG-7426

7. Lease Name or Unit Agreement Name

McBride State

8. Well Number  
#3

9. OGRID Number  
009974

10. Pool name or Wildcat  
Diablo Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Hanson Operating Company, Inc.

3. Address of Operator  
P. O. Box 1515, Roswell, NM 88202-1515

4. Well Location

Unit: Letter G : 1675 feet from the North line and 2310 feet from the East line  
Section 28 Township 10 South Range 27 East NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3810 GR

Pit or Below-grade Tank Application ☒ or Closure ☐

Pit type Workover Depth to Groundwater >100' Distance from nearest fresh water well >200' Distance from nearest surface water >1000'

Pit Liner Thickness: 12 mil Below-Grade Tank: Volume 25 bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL. ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

04/06/2007: Dug workover pit, lined with plastic and fenced. Remove Dry Hole Marker. Cut off 13 3/8" casing. Dug out cement and cut 7" casing.  
04/10/2007: MIRU. NU BOP. Build flowline to pit.  
04/11/2007: Pick up swivel and washpipe. Washed piece of dry hole marker. Pull out of hole and lay down.  
04/12/2007: Dug around casing. ND BOP. Cut casing. Found and repaired hole. Fill with 9 yards cement.  
04/13/2007: NU BOP. Pick bit and drill collars. Drill out to 620'.  
04/14/2007: Drill out to 870'. Circulate hole clean.  
04/15/2007: Drill out Plug #2 at 950'. Tag Plug #3 at 2480'. Drill to 2580'. Circulate hole clean.  
04/16/2007: Tag Plug #4 at 4640'. Drill to 5618'. Circulate hole clean.  
04/17/2007: Drill to 6000' TD. Circulate hole clean. Pull out of hole with tubing. Lay down drill collars.  
04/18/2007: Rig up wireline. Run Cement Bond Log and Gamma Ray Log. Perforate Wolfcamp formation at 5556'-5762' and 5798'-5900' with 38 holes. Rig down wireline. Test tubing.  
04/19/2007: Acidize with 5672 gallons 20% acid. Blew hole in tubing. Drop standing valve. Test for hole.  
04/20/2007: Unset packer. Pull out of hole with tubing. Lay down bad joint. Run in hole with tubing. Set packer. Swab back load. Swab test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒ a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Carol J. Smith TITLE Production Analyst DATE 2/21/2008  
Type or print name Carol J. Smith E-mail address: hanson@dfn.com Telephone No. 505-622-7330

For State Use Only

APPROVED BY: \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of Approval (if any): \_\_\_\_\_

Accepted for record - NMOCD