Form 3160-5 (August 2007)

OCD-ARTESIA UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. LC062052

6. If Indian, Allottee or Tribe Name



SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for su	ch proposals.
SUBMIT IN TRIPLICATE – Other instructions of	7. If Unit of CA/Agreement, Name and/or No.
I. Type of Well ☐ Gas Well ☐ Other	MAR 18 2008 8. Well Name and No. TAMANO (BSSC) UNIT #703
2. Name of Operator LEGACY RESERVES OPERATING LP	OCD-ARTESIA 9. API Well No. 30-015-25736
	(include area code) 10. Field and Pool or Exploratory Area
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) UNIT LETTER B, 990 FNL & 1980 FEL SECTION 11, T-18-S, R-31-E	11. Country or Parish, State EDDY COUNTY, NM
12. CHECK THE APPROPRIATE BOX(ES) TO IND	ICATE NATURE OF NOTICE, REPORT OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION
	ure Treat Reclamation Well Integrity
Subsequent Report	Construction Recomplete Otherand Abandon Temporarily Abandon
	Back Water Disposal
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) SEE ATTACHED APPROVED WAR 1 2 2008 LES BABYAK PETROLEUM ENGINEER APPROVED FOR 3 MONTH PERIOD APPROVED FOR 3 MONTH PER	
D. PATRICK DARDEN, PE	Title PETROLEUM ENGINEER
Signature 2 table for	Date 02/26/2008
THIS SPACE FOR FEDE	RAL OR STATE OFFICE USE
Approved by	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or of that the applicant holds legal or equitable title to those rights in the subject lease which we entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any part of the subject lease which we entitle the applicant to conduct operations thereon.	

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

PROCEDURE TO STIMULATE CARBONATE ZONE WITH SXE ACID Tamano (BSSC) Unit #703

- 1) Set pkr @ 8,000'.
- 2) Press TCA to 500 psig & monitor throughout job. Treat Bone Spring perfs 8,040'-8,125' w/8,000 gals acid dwn 2-7/8" tbg.
- 3) Swb back load. Rel pkr. POH w/tbg & pkr. RIH w/prod tbg, pump & rods.
- 4) RDMO PU. RWTP.

Estimate start date: 2/29/08

Note: Well is currently down with a tubing leak. Will do acid job while tubing is out of hole repairing casing leak.