Form 3160-5 (August 1999)

LINITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Do not use this form for proposals to drill or to re-enter an



FORM APROVED OMB NO. 1004-0135 EXPIRES: NOVEMBER 30, 2000

OCD-ARTES Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS

6. It Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals SUBMIT IN TRIPLICATE 7. Unit or CA Agreement Name and No. APR 29 2008 1a. Type of Well ☑ TO Gas Well Other 8 Well Name and No. OCD-ARTESIA Black Jack 1 Federal 2 2. Name of Operator 9. API Well No. **DEVON ENERGY PRODUCTION COMPANY, LP** 30-015-33383 3. Address and Telephone No. 20 North Broadway, Oklahoma City, OK 73102 405-235-3611 10. Field and Pool, or Exploratory 4. Location of Well (Report location clearly and in accordance with Federal requirements)* Ingle Wells; Brushy Canyon 1980 FSL 1980 FEL SEC 1 T24S R30E 12. County or Parish 13. State Eddy NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION Production (Start/Resume) Water Shut-Off Acidize Deepen Notice of Intent Fracture Treat Reclamation Well Integrity Alter Casing Other Add Pay Subsequent Report Casing Repair **New Construction** Recomplete Change Plans Plug and Abandon Temporarily Abandon Brushy Canyon Final Abandonment Notice Convert to Injection Plug Back Water Disposal Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof if the proposal deepen directionally or recomplete honzontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations of the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) 2/23/08 - 04/16/08 1. MIRU PU. POH w/rods & pump. NU BOPs. 2. MIRU WL. NU WL BOPE. 3. RIH w/ gauge ring & junk basket to @ 7834'. 4. RIH & perf Brushy Canyon 7768-76' @ 2 spf :16 shots; 7707-18' @ 2 spf; 18 shots. RD WL. 5. RIH w/ RBP & pkr. Set @ 7810'. PUH set pkr @ 7643'. Swab. 6 RU BJ & acidíze w/ 2K g 7.5% Pentol acid & 50 BS w/ 2% KCL wtr. RD BJ. 7. Rise pkr & set @ 7739' & RU & RIH w/ swab. Pull pkr & reset @ 7643'. 8. Rise pkr & latch on to RBP. 11.Set TAC. ND WH & unset TAC. NU BOP. Test to 2500#, ok. 12. RU BJ & frac 7768-76' w/ 49.9 bb; 1# Siberprop 16/30, 52.1 bbls 2# Siberprop 16/30, 40.7 bbl 3# Siberprop 16/30, 10.2 bbl 4# Siberprop 16/30 flush. CHC and POP. RDMO. 14. I hereby certify that the foregoing is true and correct Name Judy A. Barnett x8699 Title Regulatory Analyst Date 4/16/2008 (This space for Federal or State Office use) Approved by Title Date Conditions of approval, if any: within its jurisdiction.

*See Instruction on Reverse Side

Accepted for record - NMOCD

ACCEPTED FOR RECORD APR 2 7 1 2008 BUREAU OF LAND MANAGEMENT

CARLSBAD FIELD OFFICE