District I 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources 100 ARTESIA

JUN 2 3 2008

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

							<u> </u>					
Release Notification and Corrective Action												
						OPERA'	гor	[X] I:	nitial Report		Final Repor	
Name of Co	ompany P	enroc	oil C	prpuration	רמן	Contact A	1. 4. (Me	rch) Mer	chant			
Address P.O. BOX 2769. Hobbs NM 28241						Telephone No. (575) 492-1236						
Facility Na	me Mc N	lillan Fe	dera/	Com # 1		Facility Type Tank Authory / Pump Jack						
Surface Owner N/A Mineral Owne						Feder	a/	Leas	Lease No. NM 27642			
30-015-22384 LOCATION OF RELEASE												
Unit Letter	Unit Letter Section Township Range Feet from the No				North	South Line	Feet from the	East/West Lin	ast/West Line County			
J	14	205	276	2080		South	1980	East	G	Eddy		
Latitude Longitude												
NATURE OF RELEASE												
Type of Release Produced water + 50mc oi Volume of Release UNKNOWN Volume Recovered -												
					4411						AMT KANNIN	
Source of Release water tank, Eshaust from Engine, Stuffur Date and Hour of Occurrence Date and Hour of Discovery Nor Known Was Immediate Notice Given? Date and Hour of Discovery Nor Known Only YES, To Whom?												
Don't know- was there Yes No Not Required when acquired from Maratam												
By Whom?	acquir	ton N	ara+6	<i>a</i> a		Date and Hour N/A						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
☐ Yes 🔀 No						No						
If a Watercourse was Impacted, Describe Fully.*												
•												
Describe Cause of Broklem and Bernedial Action Taken * 4												
Describe Cause of Problem and Remedial Action Taken.* Apparently water tank had leaked of some sil on												
top ma	my ye	ou ago	· Cello	ir was co	vou	ed_Dily	spot ano	und the	cirell 1	wad.	•	
top many years ago. Cellar was covered - sily spot around the well head. Enhant furn gas motor leaving ally spot behind pumping jack.												
Describe Area	Affected a	ind Cleanup A	ction Take	en.*								
Gran	Grandes Services from Lovington removed affected dirt from all areas and hawled											
do a contract of the contract												
to Combotted Recovery Inc (CRI) on 6/17/08. Browsht clear dist & gravel.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger												
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state, or local laws and/or regulations.												
OIL CONSERVATION DIVISION												
I hol.	M. A	les Can	1		1	OIL OSTIBLETITION DIVIDION						
Signature:												
Printed Name: M. Y. (Merch) Merchant						Approved by District Supervisor:						
	Q.	D. F										
Title:	, m		<u> </u>			Approval Date	6-24.08	Expiration	n Date:	A		
E-mail Address: my mercha pennocoil. con Conditions of Approval:												
		 	(<u>, </u>	Attached Approval.						