

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

S

WELL API NO. 30-015-20277
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 7. NM-NM0405444-A
7. Lease Name or Unit Agreement Name
8. Well Number Todd 26G Federal #2 SWD
9. OGRID Number 6137
10. Pool name or Wildcat Ingle Wells; Delaware

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator Devon Energy Corporation	
3. Address of Operator 20 North Broadway, Oklahoma City OK 73102 (405) 235-3611	
4. Well Location Unit Letter G: 1980 feet from the North line and 1650 feet from the East line Section 26 Township 23S Range 31E NMPM Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

JUL 25 2008
OCD-ARTESIA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: Clean Out Sand <input checked="" type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/8/08 - OWU.
7/10/08 - Well flowing back Tied csg to flow back line & open csg.
7/12/08 - MIRU. Notified Richard Inge w/ NMOCD, Artesia.
7/15/08 - RU PU & install BOP. POOH w/ tbg & pkr. RIH w/ 20 jts tbg. OWU to tank w/ test hand.
7/16/08 - RIH w/ spear, BS & tbg. Tag pkr @ 4930'. CIBP @ 5150' w/ 230' fill on top. RIH w/ 10 stands tbg.
7/17/08 - RIH w/NC on btm bailer. RIH w/ tbg to 4930' & start bailing. Made good hole knocking bridges dn to 5019'. POOH w/
bailer. RIH w/ pkr & set @ 4327'. Test csg to 500 psi for 15 mins, good.
7/18/08 - POOH w/ tbg & pkr. RIH w/ WL entry guide, pkr, ON/Off tool, w/ 1.5" F-Nipple, 2 7/8" PH6 Box x 2 3/8" 8 RD pin, 25 jts 2
7/8" 6.5# IPC tbg, 2 7/8" CS Hydrill box x 2 7/8" PH6 Pin, 107 jts 2 7/8" 6.5# IPC CS Hydrill tbg, 2 7/8" EUE x 2 7/8" CS Hydrill pin, 2
jts 2 7/8" J-55 IPC tbg. Set pkr & rlse On/Off tool. Circ hole w/ 2% KCL pkr fluid. Test csg to 500 psi & chart for 30 mins. ND BOP.
Flange up WH.
7/19/08 - RU PT. Chart recorder, test csg to 500 psi & chart for 30 mins. Witnessed by Richard Inge w/ NMOCD. Rebuilt WH & RD
PU. CO fill to 5019'. RDMO.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Judy A. Barnett TITLE Regulatory Analyst DATE 7/24/08

Type or print name Judy A. Barnett E-mail address: Judith.Barnett@dmn.com PHONE: X8699

For State Use Only

APPROVED BY: _____ TITLE _____ DATE _____

Accepted for record - NMOCD