

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



|  |
|--|
| WELL API NO.<br>30-015-05184   |
| 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>NMLC-029395-B  |
| 7. Lease Name or Unit Agreement Name<br>Turner B   |
| 8. Well Number<br>5  |
| 9. OGRID Number<br>14591   |
| 10. Pool name or Wildcat<br>Grayburg-Jackson   |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐

2. Name of Operator  
Merit Energy Company

3. Address of Operator  
13727 Noel RD. Ste 500, Dallas, TX 75240

4. Well Location  
Unit Letter   : 1980    feet from the    S line and    660    feet from the    W line  
Section    17 Township    17-S Range    31-E NMPM County    Eddy, NM

SEP 18 2008  
OCD-ARTESIA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type    Depth to Groundwater    Distance from nearest fresh water well    Distance from nearest surface water   

Pit Liner Thickness:    mil Below-Grade Tank: Volume    bbls; Construction Material   

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO:                        |   | SUBSEQUENT REPORT OF:                            |   |
|--|---|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>           | ALTERING CASING <input type="checkbox"/>    |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/> | P AND A <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | MULTIPLE COMPL <input type="checkbox"/>   | CASING/CEMENT JOB <input type="checkbox"/>       |   |
| OTHER: <input type="checkbox"/>                |   | OTHER: <input type="checkbox"/>                  |   |

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please see attached work

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Kristin Hodge TITLE Regulatory Analyst DATE 09/15/2008

Type or print name Kristin Hodge E-mail address: Kristin.Hodge@meritenergy.com Telephone No. 972-628-1467

For State Use Only **Accepted for record**

APPROVED BY: NMOCD TITLE    DATE 9/18/08

Conditions of Approval (if any):

4

**08/20/08:** ARRIVE ON LOC. – HOLD 5 MIN. SAFETY MEETING; REPAIR TIRES ON RIG & MOVE RIG & PXA EQUIP. TO NEW LOCATION; WAIT ON RIG ANCHORS TO BE SET; SPOTTED RIG & RU BCM & ASSOCIATES, INC. (HAD A LOT OF TROUBLE SPOTTING EQUIP. DUE TO SMALL LOC. & GETTING STUCK IN SAND); WILL RUN TBG. IN THE AM; SDFN.

**08/21/08:** ARRIVE ON LOC. – HOLD 5 MIN. SAFETY MEETING; OPEN WELL & BLEED DOWN; ND WELLHEAD & NU BOP'S; RU FLOOR & TONGS & GO TO GET STEEL PIT; SPOT TANK ON LOC. – GOT STUCK IN SAND & HAD TO GET BACKHOE TO GET TRUCK OUT OF SAND; PU TBG. OFF OF FLOAT & RIH W/ 4-1/2" CIBP & TBG. – NEEDED MORE TBG.; ROUSTABOUT WAS SUPPOSE TO BRING TBG. TO LOC. BUT DID NOT; LOCATED MERIT CO. MAN & SAID WE HAD TO GET TBG. ON OUR OWN; WENT TO YARD & LOAD & HAUL ADD'L TBG. TO LOC.; PU & CIH W/ TBG. & SET CIBP @ 3304'; BEGIN CIRC. WELL W/ PXA MUD & CHAIN BROKE ON PUMP TRUCK; CWI & SDFN.

**08/22/08:** ARRIVE ON LOC. – HOLD SAFETY MEETING; OPEN WELL – NO PRES.; FIX PUMP TRUCK & MIX & PUMP A 25 SX. CMT. PLUG ON TOP OF CIBP @ 3304'; POOH W/ TBG. & WOC; RIH W/ TBG. & TAG TOP OF CMT. PLUG @ 2926'; POOH LAYING DOWN TBG. TO 2415'; MIX & PUMP A 25 SX. CMT. PLUG @ 2415'; POOH W/ TBG. & WOC; CWI & SDFW

**08/25/08:** ARRIVE ON LOC. – HOLD SAFETY MEETING; OPEN WELL – NO PRES.; RUWL & RIH & TAG TOP OF 2415' CMT. PLUG @ 2120'; POOH & RDWL; POOH LAYING DOWN TBG. ON TRAILER; ND BOP'S & WELLHEAD – HAD A LOT OF TROUBLE TAKING CAP OFF HEAD & HAD TO FINALLY CUT THE SAME; NU CSG. EQUIP. & ATTEMPT TO PULL CSG. OUT OF SLIPS – SLIPS STUCK IN HEAD; LEFT SOAKING IN OIL OVERNIGHT; CWI & SDFN.

**08/26/08:** ARRIVE ON LOC. – HOLD SAFETY MEETING; OPEN WELL – NO PRES.; RUWL & CSG. CUTTER & RIH W/ CUTTER TO 1700'; PULL UP TO COLLAR @ 1680' & CUT CSG.; POOH & RDWL; POOH LAYING DOWN 4-1/2" CSG. – 54 JTS. TOTAL; ND CSG. EQUIP. & NU WELLHEAD & BOP'S; RIH W/ TBG. TO 1732' & MIX & PUMP A 30 SX. CMT. PLUG @ 1732'; POOH W/ TBG. & WOC; CWI & SDFN.

**08/27/08:** ARRIVE ON LOC. – HOLD SAFETY MEETING; OPEN WELL – NO PRES.; RIH W/ TBG. & TAG TOP OF 1680' CMT. PLUG @ 1480'; POOH LAYING DOWN TBG. ON TRAILER; DIG OUT 8-5/8" CSG. HEAD; RUWL & PERF. GUN & RIH & PERF. SQZ. HOLES @ 575'; POOH & RDWL; PU 7" PKR. & RIH W/ PKR. & TBG. TO 340'; SET PKR. & EST. INJ. RATE; MIX & SQZ. A 50 SX. CMT. PLUG @ 575'; CWI & WOC; SHUT DOWN DUE TO HEAVY RAINS.

**08/29/08:** ARRIVE ON LOC. – HOLD SAFETY MEETING; OPEN WELL – NO PRES.; RUWL & PERF. GUN & RIH & TAG TO OF 575' CMT. PLUG @ 390'; POOH W/ PERF. GUN & PERF. SQZ. HOLES @ 250'; POOH & RDWL; PU PKR. & RIH W/ PKR. & 1 JT. TBG. TO 30'; SET PKR. & EST. INJ. RATE & MIX & SQZ. A 30 SX. CMT. PLUG @ 250' (WELL DID NOT CIRC.); REL. PKR. & POOH W/ TBG. & PKR. & WOC; RUWL & RIH TO 250' – DID NOT TAG CMT. PLUG; POOH & RDWL; PU PKR. & RIH W/ PKR. & TBG.; TO 30'; SET PKR. & MIX & SQZ. A 30 SX. CMT. PLUG @ 250'; CWI & WOC; SDFN.

**Accepted for record  
NMOCD**

**08/29/08:** ARRIVE ON LOC. – HOLD SAFETY MEETING; OPEN WELL – NO PRES.; RIH W/ TBG. TO 250' – DID NOT TAG CMT. PLUG; MIX & PUMP A 25 SX. CMT. PLUG @ 250'; POOH W/ TBG. & WOC; RIH W/ TBG. – DID NOT TAG CMT. PLUG; MIX & PUMP A 25 SX. CMT. PLUG @ 250'; POOH W/ TBG. & WOC; CWI & SDFH.

**09/02/08:** ARRIVE ON LOC. – HOLD SAFETY MEETING; OPEN WELL – NO PRES.; RUWL & RIH & TAG CMT. PLUG @ 35'; POOH & RDWL; RIH W/ 1 JT. TBG. & PRES. UP ON CMT. PLUG – HELD OK; MIX & CIRC. CMT. TO SURF.; POOH LAYING DOWN TBG.; RDMO & ROAD RIG & PXA EQUIP. TO THE TURNER "A" #014; ARRIVE ON LOC. & OPEN WELL & BEGIN TO BLEED DOWN; NU WELL TO FRAC TANK ON LOC. & CON'T TO BLEED DOWN WELL; SDFN.

**Accepted for record  
NMOCD**