Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

surface. When cement returns to surface, close ball valve and allow cement to flow outside

OCD-ARI	ESTA	FORM APPROVED
	1	PORMI APPROVED
	1 "	OM B No. 1004-0137
	J	ON D NO. 100+0137
*	1	Expires March 31, 200

OCT 07 2008

5. Lease Serial No. NMLC 050797 SUNDRY NOTICES AND REPORTS ON WELLS If Indian, Allottee or Tribe Name OCD-ARTER not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE- Other instructions on reverse side. Gas Well □□ Well Name and No. Russell USA #24 2. Name of Operator Apollo Energy, LP API Well No. 30-015-02373 3a Address 3b Phone No. (include area code) 337-502-5227 4823 Ihles Rd., Lake Charles, LA 70605 10. Field and Pool, or Exploratory Area Russell - Yates 4 Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 2322 FNL 2333 FEL Sec 13 Twup 20S R-28E **Eddy County, NM** 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Production (Start/Resume) Water Shut-Off Deenen Notice of Intent Alter Casing Reclamation Well Integrity Fracture Treat Casing Repair New Construction Recomplete Śubsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 1. TIH with tubing and bailer. Clean and bail hole to 849. 2. Move on Gray Wireline perforating truck. Perforate 7" casing from 200-202 with 8 holes and 100-102 with 8 holes. R/D and move off. 3. Run 4 1/2" 11.6 #/ft casing with automatic fill-up float shoe inside 7" to TD - 849. Tag bottom to check for fill. It will be important to wash below Yates interval 824 - 849. 4. Land casing on casing hanger. Gerry Guye, Deputy Field Inspector 5. Rig down pulling unit and move off location. 6. Dig hole for 55 gal drum. Install 55 gal drum in tank. Install 2" nipple on 7" with valve. NMOCD-District II ARTESIA Weld plate on 7" X 4 1/2" top. 7. Move on Halliburton and water trucks, fill hole with gelled water. Circulate and establish circulation noting the volume fill to return gel pill. Have sufficient vacuum truck capacity to catch returns from circulation. 8. Mix and circulate Class C cement per recommendation down 4 1/2 until cement returns are at

SUBJECT TO LIKE APPROVAL BY STATE

4. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		
Thomas G. Wright	Title Vice-Presid	lent
Signature 2 May	Date	09/22/2008 APPROVED
THIS SPACE FO	R FEDERAL OR STATE (OFFICE USE
Approved by	name of the sport of Fitle	Date OCT 5 2008
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		JAMES A. AMOS

7". Displace plug with water.

9. WOC. Secure pipe and move off location.