| Submit 3 Còpies To Appropriate District | State of New Mexico | Form C-103 |
|--|---|--|
| Office District I | Energy, Minerals and Natural Resourc | es June 19, 2008 |
| 1625 N French Sr , Hobbs, NM 88240 | | WELL API NO. |
| District II 1301 W Grand Ave, Artesia, NM 8821 | OIL CONSERVATION DIVISION | 30-015-33450 6. Indicate Type of Lease |
| District III | 1220 South St. Francis Dr. | STATE S FEE |
| 1000 Rio Brazos Rd, Aztec, NM 87410 District IV. | Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| 1220 S St. Francis Dr , Santa Fe, NM | , | State on & sas Evase No. |
| 87505 | OWNERS AND DEPONTS ON WELLS | |
| I . | OTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A | 7. Lease Name or Unit Agreement Name |
| | PLICATION FOR PERMIT" (FORM C-101) FOR SUCH | Center Sixteen SWD |
| PROPOSALS) | | 8. Well Number |
| 1. Type of Well: Oil Well | Gas Well Other SWD OCT 2 4 20 | |
| 2. Name of Operator | | 9. OGRID Number |
| M | Iarbob Energy Corporation | 14049 |
| 3. Address of Operator | | 10. Pool name or Wildcat |
| PO Box | x 227, Artesia, NM 88211-0227 | SWD; Delaware |
| 4. Well Location | | |
| Unit LetterK | _:2640feet from theSouth line at | nd2640feet from theWestline |
| Section 16 | Township 25S Range 28E | NMPM Eddy County |
| | 11. Elevation (Show whether DR, RKB, RT, G | R, etc.) |
| | 2991' GR | |
| | | |
| 12. Checl | k Appropriate Box to Indicate Nature of No | otice, Report or Other Data |
| NOTIOE OF | INTENTION TO | OUDOFOLIENT DEDORT OF |
| | INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK [| | _ |
| | | CE DRILLING OPNS. P AND A |
| PULL OR ALTER CASING [| ☐ ·MULTIPLE COMPL ☐ CASING/C | EMENT JOB |
| DOWNHOLE COMMINGLE [| | |
| | | |
| OTHER: | □ OTHER: | Add additional disposal interval |
| | | Add additional disposal interval ils, and give pertinent dates, including estimated date |
| 13. Describe proposed or cor of starting any proposed | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completio | |
| 13. Describe proposed or cor of starting any proposed | mpleted operations. (Clearly state all pertinent deta | ills, and give pertinent dates, including estimated date |
| 13. Describe proposed or cor of starting any proposed | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completio | ills, and give pertinent dates, including estimated date |
| 13. Describe proposed or composed of starting any proposed or recompletion. | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completio いひ - 923-A | ills, and give pertinent dates, including estimated date |
| 13. Describe proposed or composed of starting any proposed or recompletion. | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completio | ills, and give pertinent dates, including estimated date |
| 13. Describe proposed or composed of starting any proposed or recompletion. | work). SEE RULE 1103. For Multiple Completio D - 928-A vare Sand disposal interval as follows: | ills, and give pertinent dates, including estimated date |
| 13. Describe proposed or composed of starting any proposed or recompletion. | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion $\mathbf{D} - 928^{-}\mathbf{A}$ ware Sand disposal interval as follows: | nils, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion |
| 13. Describe proposed or conformal of starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw | work). SEE RULE 1103. For Multiple Completio D - 928-A vare Sand disposal interval as follows: | ails, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion al NE Fe 7 ½% HCl acid. |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K ga gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. In | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion of NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K ga 28 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. It erry Guye w/ OCD on 10/9/08 of pressure test scheen | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion of NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K ga gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. In | all NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Ruled for 10/10/08. He instructed us to go |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K ga 28 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. It erry Guye w/ OCD on 10/9/08 of pressure test scheen | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion of NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K ga 28 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. It erry Guye w/ OCD on 10/9/08 of pressure test scheen | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion of the state o |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K ga 28 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. It erry Guye w/ OCD on 10/9/08 of pressure test scheen | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion of NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K ga 28 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. It erry Guye w/ OCD on 10/9/08 of pressure test scheen | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion all NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go 3.*** ACCEPTED FOR RECORD |
| 13. Describe proposed or conformal of starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS proposed or conformal or con | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completio D - 928-A vare Sand disposal interval as follows: P @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K ga 28 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. Herry Guye w/ OCD on 10/9/08 of pressure test scheor run it without a witness & submit the chart w/ C-10 | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion all NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go 3.*** ACCEPTED FOR RECORD Gerry Guye. Deputy Field Increase. |
| 13. Describe proposed or conformal of starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS proposed or conformal or con | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completio D - 928-A vare Sand disposal interval as follows: P @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K ga 28 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. Herry Guye w/ OCD on 10/9/08 of pressure test scheor run it without a witness & submit the chart w/ C-10 | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion all NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go 3.*** ACCEPTED FOR RECORD |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge ahead and p | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completio D - 928-A vare Sand disposal interval as follows: P @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K ga 28 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. Herry Guye w/ OCD on 10/9/08 of pressure test scheor run it without a witness & submit the chart w/ C-10 | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion all NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go 3.*** ACCEPTED FOR RECORD Gerry Guye, Deputy Field Inspector NMOCD-District II ARTESIA |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge ahead and p | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P @ 3910'. ware @ 5060' - 5963' (200 shots). Acdz w/ 10K gand 208 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. It earry Guye w/ OCD on 10/9/08 of pressure test schedurum it without a witness & submit the chart w/ C-10 Rig Release Date: | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion all NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go 3.*** ACCEPTED FOR RECORD Gerry Guye, Deputy Field Inspector NMOCD-District II ARTESIA |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge ahead and p | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: 2 @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K gand gall fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. If earry Guye w/ OCD on 10/9/08 of pressure test scheor run it without a witness & submit the chart w/ C-10 Rig Release Date: | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion all NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go 3.*** ACCEPTED FOR RECORD Gerry Guye, Deputy Field Inspector NMOCD-District II ARTESIA owledge and belief. |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge ahead and p | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: 2 @ 3910'. vare @ 5060' - 5963' (200 shots). Acdz w/ 10K gand gall fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. If earry Guye w/ OCD on 10/9/08 of pressure test scheor run it without a witness & submit the chart w/ C-10 Rig Release Date: | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion all NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go 3.*** ACCEPTED FOR RECORD Gerry Guye, Deputy Field Inspector NMOCD-District II ARTESIA |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 - Drill out CIBF 10/2/08 - Perf the Delaw 10/4/08 - Frac w/ 12349 10/10/08 - Set NP PLS p ***Notified Ge ahead and p | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P(@ 3910'. ware @ 5060' - 5963' (200 shots). Acdz w/ 10K gate 208 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. It erry Guye w/ OCD on 10/9/08 of pressure test scheor run it without a witness & submit the chart w/ C-10 Rig Release Date: TITLE Production Analy | ails, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion al NE Fe 7 1/2% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go 3.*** ACCEPTED FOR RECORD Gerry Guye, Deputy Field Inspector NMOCD-District II ARTESIA DATE10/22/08 |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge ahead and p | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P(@ 3910'. ware @ 5060' - 5963' (200 shots). Acdz w/ 10K gate 208 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. It erry Guye w/ OCD on 10/9/08 of pressure test scheor run it without a witness & submit the chart w/ C-10 Rig Release Date: TITLE Production Analy | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion all NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go 3.*** ACCEPTED FOR RECORD Gerry Guye, Deputy Field Inspector NMOCD-District II ARTESIA |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 - Drill out CIBF 10/2/08 - Perf the Delaw 10/4/08 - Frac w/ 12349 10/10/08 - Set NP PLS p ***Notified Ge ahead and p | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P(@ 3910'. ware @ 5060' - 5963' (200 shots). Acdz w/ 10K gate 208 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. It erry Guye w/ OCD on 10/9/08 of pressure test scheor run it without a witness & submit the chart w/ C-10 Rig Release Date: TITLE Production Analy | ails, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion al NE Fe 7 ½% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Huled for 10/10/08. He instructed us to go 3.*** ACCEPTED FOR RECORD Gerry Guye, Deputy Field Inspector NMOCD-District II ARTESIA DATE10/22/08 |
| 13. Describe proposed or corof starting any proposed or recompletion. Added additional Delaw 9/30/08 – Drill out CIBF 10/2/08 – Perf the Delaw 10/4/08 – Frac w/ 12349 10/10/08 – Set NP PLS p ***Notified Ge ahead and p | mpleted operations. (Clearly state all pertinent deta work). SEE RULE 1103. For Multiple Completion D - 928-A vare Sand disposal interval as follows: P(@ 3910'. ware @ 5060' - 5963' (200 shots). Acdz w/ 10K gate 208 gal fluid & 199419# sand. AIR 40.6 BPM. AIP pkr @ 2764'. Pressure tested to 300# for 30 min. It erry Guye w/ OCD on 10/9/08 of pressure test scheor run it without a witness & submit the chart w/ C-10 Rig Release Date: TITLE Production Analy | alls, and give pertinent dates, including estimated date ns: Attach wellbore diagram of proposed completion al NE Fe 7 1/2% HCl acid. 3441#. ISDP 743#. Held OK. (See chart attached). Ruled for 10/10/08. He instructed us to go 3.*** ACCEPTED FOR RECORD Gerry Guye, Deputy Field Inspector NMOCD District II ARTESIA DATE 10/22/08 @marbob.com PHONE: _(575) 748-3303_ |

