

Office

Energy, Minerals and Natural Resources

Revised June 10, 2003

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87418

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

AUG 2003
RECEIVED
OCD - ARTESIA

OIL CONSERVATION DIVISION

1200 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-005-63073

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

VB-0427

7. Lease Name or Unit Agreement Name

Hanlad AKZ State

8. Well Number

3

9. OGRID Number

025575

10. Pool name or Wildcat

Acme San Andres, Southeast

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☐ Plug & Abandon

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter L : 2310 feet from the South line and 330 feet from the West lineSection 13Township 8S Range 27E

NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3949' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7-16-2003 - Moved in pulling unit and plugging equipment. Spotted equipment.

7-17-2003 - Moved pumping unit off hole. Rigged up pulling unit. Jarred on pump for 2 hours. POOH with rods. Left cups with standing valve in hole. Rigged down rod equipment. Nippled down wellhead and nipped up BOP. Rigged up floor and tubing equipment. Shut well in for night.

7-18-2003 - POOH with tubing. RIH with 10 joints. Shut well in. Rig repair.

7-19-22-2003 - RIH to 2200'. Circulated hole with plugging mud. Spotted 25 sacks Class C Neat cement. POOH with 50 joints. Shut well in for night. WOC.

7-23-2003 - RIH with tubing and tagged plug at 1994'. Circulated hole with plugging mud. Pulled up hole to 535'. Circulated 55 sacks Class C Neat cement from 535' to surface. POOH with tubing and rigged down tubing equipment and floor. Nippled down BOP. Topped off cement. Rigged down pulling unit and plugging equipment. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 7-22-2003.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Donna Clack*TITLE REGULATORY COMPLIANCE TECH DATE 7-31-03Type or print name DONNA CLACK

E-mail address:

Telephone No 505-748-1471

(This space for State use)

APPROVED BY

TITLE

DATE

Conditions of approval, if any:

[Signature]

APPROVED OCT 15 2003