

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DEC 12 2008

OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

ASE80900253708

Name of Company COG OPERATING LLC 229137		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address 550 W. Texas, Suite 1300 Midland, TX 79701		Contact Kanicia Carrillo			
Facility Name - Berry A Federal 7		Telephone No. 432-685-4332			
		Facility Type- Battery			
Surface Owner BLM		Mineral Owner		Lease No.API# 30-015-29564	

3001529564
LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	21	17S	30E	330	North	2110	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release- Oil	Volume of Release-3 bbls	Volume Recovered- none
Source of Release- 4 x 20 Heater	Date and Hour of Occurrence- 12/06/08- 7:00pm	Date and Hour of Discovery 12/06/08-7:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Duncan Whitlock w/BLM & Mike Bratcher w/OCD.	
By Whom? Kanicia Carrillo	Date and Hour December 8, 2008, 4:56pm.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The 4 x 20 heater caught on fire. A hole appeared in the top section of the heater. The burner was lit in the heater for operational purposes and therefore was the ignition source for the fire. Loco Hills Fire Department came out and extinguished the fire. Heater was repaired

Describe Area Affected and Cleanup Action Taken.*

Top section of heater. The oil that reached the ground was burning. The only clean up was to back drag the charred ground.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Kanicia Carrillo		Approved by District Supervisor: 	
Title: Regulatory Analyst		Approval Date: 1-2-9	Expiration Date: N/A
E-mail Address: kandicarrillo@conchoresources.com		Conditions of Approval: N/A	Attached <input type="checkbox"/> N/A
Date: 12/09/08 Phone: 432-685-4332			

* Attach Additional Sheets If Necessary