

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505



WELL API NO. 30-005-63061
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2982
7. Lease Name or Unit Agreement Name Quincy AMQ State
8. Well Number #11
9. OGRID Number 009974
10. Pool name or Wildcat Acme San Andres Southeast

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3934' GR

Pit or Below-grade Tank Application or Closure

Pit type _____ Depth to Groundwater >100' Distance from nearest fresh water well >2 miles Distance from nearest surface water >10 miles

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well Gas Well Other

2. Name of Operator
Hanson Operating Company, Inc.

3. Address of Operator
P. O. Box 1515, Roswell, NM 88202-1515

JAN 05 2009

OCD-ARTESIA

4. Well Location
Unit Letter K : 1650 feet from the South line and 1650 feet from the West line
Section 12 Township 8 South Range 27 East NMPM Chaves County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING MULTIPLE COMPL
OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. P AND A
CASING/CEMENT JOB
OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Plug and abandon well as follows:

11/5/2008: MIRU. SD.

11/6/2008: Set CIBP at 2050'. Circulate hole with 10# brine with 12.5# per barrel salt water gel. Spot 25 sack cement plug on CIBP. Perforate 4 squeeze holes at 460'. Pump 125 sack cement plug and circulate to surface. Well plugged and abandoned. Witnessed by Phil Hawkins.

Clean and remediate location, and set Dry Hole Marker by January 31, 2009.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .

SIGNATURE Carol J. Smith TITLE Production Analyst DATE 12/31/2008
Type or print name Carol J. Smith E-mail address: hanson@dfn.com Telephone No. 505-622-7330

For State Use Only **Accepted for record**
APPROVED BY: NMOCD TITLE _____
Conditions of Approval (if any): _____

Approved for plugging of well bore only.
Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms: www.emr.d.state.nm.us/oed.

DATE 1/6/09