	•	COUT 1 NIMO
Submit 3 Copies To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resourc	
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S St Francis Dr , Santa Fe, NM 87505	AND DEDONTS ON MEN IS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Caffall FD  8. Well Number
	Well 🛛 Other	1
2. Name of Operator Yates Petroleum Corporation		9. OGRID Number 025575
3. Address of Operator 105 South Fourth Street, Artesia, NM 88	3210	10. Pool name or Wildcat Undes. Upper Penn; Canyon
4. Well Location Unit Letter O: 660	feet from the South line and	1980 feet from the East line
Section 15	Township 17S Range 26	
11.	Elevation (Show whether DR, RKB, RT, G 3354'GR	R, etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
TEMPORARILY ABANDON CHA	JG AND ABANDON ⊠ REMEDIAL COMMENC	SUBSEQUENT REPORT OF: WORK
OTHER:	☐ OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
		TIH to retrieve an RBP somewhere between 7786'
3. RU WL to freepoint the 5-1/2" casing,	cut the casing at the freepoint. POOH with	n set a CIBP at 6456' and cap with 35' cement. n cutter and casing. 190'. Circulate tubing clean and WOC 4 hrs and tag
5. Spot a 40 sx cement plug from 4325'-4 necessary.	-	te tubing clean and WOC 4 hrs and tag plug. Reset if
<ol><li>Spot a 45 sx cement plug from 2305'-2 Reset if necessary.</li></ol>	425' across the Glorieta top at 2357'. Circ	culate tubing clean and WOC 4 hrs and tag plug.
7. Spot a 40 sx cement plug from 1354'-1	454' across the Intermediate casing shoe a re off the well and secure the well and loca	t 1404'. Circulate tubing clean and WOC 4 hrs and tion. Fill out paperwork to assign the well over to the
	Rig Release Date:	Approval Granled providing work
Spud Divotily OCD 24 hrs. pr To any work done.	ior	is complete by
	is true and complete to the best of my kno	weldge and helief
1 horses county that the information above	N	micage and coner.

APPROVED BY: DATE 1/7/09
Conditions of Approval (if any):

Type or print name \_\_\_\_

Tina Huerta E-mail address: <u>tınah@yatespetroleum.com</u> PHONE:

TITLE Regulatory Compliance Supervisor DATE January 6, 2009



