

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

MAR 02 2009

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-00137
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Pit <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Slayton Resources, Inc.		6. State Oil & Gas Lease No. Kelly A State
3. Address of Operator P. O. Box 2035, Roswell, NM 88202-2035		7. Lease Name or Unit Agreement Name 8645-1
4. Well Location Unit Letter <u>B</u> : <u>990</u> feet from the <u>North</u> line and <u>2310</u> feet from the <u>East</u> line Section <u>26</u> <u>10S</u> Township <u>26E</u> Range <u>NMPM</u> County <u>Chaves</u>		8. Well Number
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 196015
		10. Pool name or Wildcat Brown Queen Grayburg

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**  
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

**SUBSEQUENT REPORT OF:**  
REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: Close Pit ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Remove soil from pit down to clean soil. Take removed soil to Gandy Marley disposal facility. Take/send soil sample from pit to Trace Analysis. Send results of soil analysis to OCD. Upon confirmation from OCD we will install liner, acquire clean soil, backfill and level area. We will send a C-141 to the OCD upon completion.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE A. D. Allison TITLE Vice-President DATE 02-26-09

Type or print name A. D. Allison E-mail address: \_\_\_\_\_ PHONE: 575-623-7185  
For State Use Only

APPROVED BY: \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of Approval (if any):

*Handwritten signature/initials*