

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-015-03021 23021

5. Indicate Type of Lease

STATE ☒FEE ☐

6. State Oil & Gas Lease No.

V-2991

7. Lease Name or Unit Agreement Name

Milepost Com

8. Well No.

1

9. Pool name or Wildcat

Milepost Morrow

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

Type of Well:

OIL
WELL ☐GAS
WELL ☒

OTHER

Name of Operator

JFG Enterprise

Address of Operator

P.O. Box 100, Artesia, NM 88210

Well Location

Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line

Section 36Township 26SRange 25E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3393.DF

1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

REFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐WILL OR ALTER CASING ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☒CASING TEST AND CEMENT JOB ☐OTHER: ☐

2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-30-94 Move in, rig up, bleed well back.

2-1-94 Kill well, put on BOP, pull tubing, set cast iron bridge plug at 10,000'. Shut down.

2-2-94 Ran tubing, circulated mud, spot 25 sacks cement on CI bridge plug from 10,000' to 9760', pull tubing to 7500', spot 25 sacks from 7500' - 7260', pull tubing to 5250', spot 25 sacks from 5250' - 5000', pull tubing out. Shut down.

2-3-94 Tag cement @ 5000'. Freepoint 5-1/2" casing @ 4800', cut & shut down.

2-5-94. Pull & lay down 5-1/2" casing, run tubing to 4850', spot 35 sacks cement @ 4850' to 4650', pull tubing to 1800'. Shut down.

2-6-94 Spot 25 sacks from 1800' to 1675', pull tubing to 400', spot 25 sacks @ 400' to 275', pull tubing to 60', circulate 15 sacks to surface, cut off wellhead, put in marker, fill pits, rig down, move off. Used class "C" cement. Mud 25# per barrel. Salt gel mud. 1-5-95 Cut Anchors. Clean Location.

Stock Tanks on location will be used as Fresh water Storage for Mary Foster, (Foster Ranches) 314 Dell City, TX, 79837, 915-964-2865, per Authority of Tim Gumm, Supervisor O.C.D. District II.

hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. T. Jackson

TITLE

Partner

DATE

4-4-95

TYPE OR PRINT NAME

J.T. Jackson

TELEPHONE NO. 746-9680

This space for State Use

APPROVED BY

Ron Livingston

TITLE

Field Rep

DATE

7-13-95

CONDITIONS OF APPROVAL, IF ANY:

NEW MEXICO OIL CONSERVATION DIVISION

P.O. DRAWER DD

ARTESIA, NEW MEXICO 8821

151

DATE June 14, 1995

JFG EnterpriseP.O. Box 100Artesia, NM 88210

Re: Plugging Reports

Gentlemen:

Form C-103 Report of Plugging for your Milepost C #1 A-36-26-25
Lease Well No. Ut. S-T-R

cannot be approved until an N.M.O.C.D. representative has made an inspection of the location and found it to be cleared to comply with Division Rules and Regulations. Please check each item in the space provided to indicate that the work has been done.

- (✓) 1. All pits have been filled and leveled.
- (✓) 2. Rat hole and cellar have been filled and leveled.
- (✓) 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete. It must show the quarter-quarter section or unit designation, section, township and range numbers which have been permanently stenciled or welded on the marker.
- (✓) 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- (✓) 5. The dead men and tie downs have been cut and removed.
- (✓) 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved

When all of the work outlined above has been done, please notify this office by filling in the blank form below and returning this letter to us so that our representative will not have to make more than one trip to the location.

Location clean ready to release

*a 500 & 300 BBL tank location
(I talked with land owner)
And a deal was made with J.T. Jackson
For the tanks to be left at location
7-13-95 *Mr. May Foster**

OIL CONSERVATION DIVISION

Ray Smith
OIL AND GAS INSPECTOR

FILL IN BELOW AND RETURN

RECEIVED

I certify that the above work has been done and the above mentioned lease is ready for your inspection and approval. *New Name JFG Enterprise LTD. Co.*

CON. DIV.
ARTESIA

JFG Enterprise
NAME
J.T. Jackson
TITLE
president

Mar 05 09 12:14p

Rhonda Becker

4326844369

p. 1

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-03021
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2991
7. Lease Name or Unit Agreement Name Milepost C
8. Well No. 1
9. Pool name or Wildcat Milepost Morrow

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	Name of Operator JFG Enterprise
Address of Operator P.O. Box 100, Artesia, NM 88210	Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line

Section <u>36</u>	Township <u>26S</u>	Range <u>25E</u>	NMPM	Eddy	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3393 DF					

1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

-) 12-1-94 Set CI Bridge Plug @ 10000'
-) 12-2-94 Ran Tubing, Circ. Mud, Spot 25 sx cement on CI Plug from 10000' - 9760'. Pull Tbg. to 7500'. Spot 25 sx from 7500' - 7260'. Pull Tbg. to 5250'. Spot 25 sx from 5250' - 5000'. Pull Tbg. Shut Down.
-) 12-3-94 Tag Cement @ 5000'. Freepoint 5-1/2" Casing @ 4800' Cut & Shut Down.
-) 12-5-94 Pull & Lay Down 5-1/2" Casing. Run Tbg. to 4850'. Spot 35 sx Cement 4850 - 4650'. Pull Tubing to 1800'. Shut Down.
-) 12-6-94 Spot 25 sx from 1800' - 1675'. Pull Tbg. to 60'. Circ. 15 sx to Surface cut off Wellhead. Install Marker, fill Pits, Rig Down. Move off. Class C Cement. Mud 25# per bbl. salt get.
-) 1-5-95 Cut anchors. Clean location. Stock tanks on location will be used as fresh water storage for Mary Foster (Foster Ranches) 314 Dell City, Tx. 79837, 915-964-2865 per authority of Tim Gumm, Supervisor OCD District II.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. T. Jackson TITLE Partner DATE 1-16-95
TYPE OR PRINT NAME J. T. Jackson TELEPHONE NO. 746-9680

(This space for State Use)

APPROVED BY Man Jiminto TITLE Field Rep DATE 7-17-95
CONDITIONS OF APPROVAL, IF ANY:

P.O. DRAWER DD
ARTESIA, NEW MEXICO 88210

VTE June 14, 1995

JFG EnterpriseP.O. Box 100Artesia, NM 88210

Re: Plugging Reports

Gentlemen:

Form C-103 Report of Plugging for your Milepost C #1 A-36-26-25
Lease Well No. Ut. S-T-R


cannot be approved until an N.M.O.C.D. representative has made an inspection of the location and found it to be cleared to comply with Division Rules and Regulations. Please check each item in the space provided to indicate that the work has been done.

- (✓) 1. All pits have been filled and leveled.
- (✓) 2. Rat hole and cellar have been filled and leveled.
- (✓) 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete. It must show the quarter-quarter section or unit designation, section, township and range numbers which have been permanently stenciled or welded on the marker.
- (✓) 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- (✓) 5. The dead men and tie downs have been cut and removed.
- (✓) 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by fillin in the blank form below and returning this letter to us so that our representative will not have to make more than one trip to the location.

OIL CONSERVATION DIVISION

FILL IN BELOW AND RETURN

I certify that the above work has been done and t
for your inspection and approval.

KJ 7-13-95

TO: Jackie

From: D.G. Becker

432 934 7042