Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR N.M. DIV-Dist. 2 BUREAU OF LAND MANAGEMEN 301 W. Grand Avenue Expires SUNDRY NOTICES AND REPORTS ON WANTESIA, NM 88210

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

Do not use this form for proposals to drill or to re-enter an

NM-12246

abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name	
				N/A	greement, Name and/or No.
OURNIT IN TRIPLICATE Of the second of the se				N/A	groomand management
SUBMIT IN TRIPLICATE - Other Instructions on reverse side 1. Type of Well				8. Well Name and No.	
Oil Well	x Gas Well	Other	Injection	OAKASON	NV FEDERAL #1
2. Name of Operator				9. API Well No	
Yates Petroleum Corporation				30-015-23438	
3a Address 3b. Phone No. (include area code) 505-748-1471 RECEIVED				10. Field and Po	ol, or Exploratory Area
4. Location of Well (Footage, Se		505-748-1471	RECEIVED	HOAG TANK	MORROW
4. 200dion of from h botage, de	c., r.,r., w., or curvey bescrip	ouon,	NOV 2 5 2003	11. County or Pa	
660' FSL & 2310' FEL	Section 27-T19	S-R24E UNIT O	1	===× 00!!!	
40 00504 455	DODDIATE DOV(EQ) TO	NIDIO ATE MATURE OF	OCD-ARTESIA	EDDY COUI	NIY, NM
TYPE OF SUBMISSION	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR OTHER TYPE OF ACTION	CDATA	
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
		_		Well Integrity	
Subsequent Report	Alter Casing	Fracture Treat	Reclamation		
Final Abandonment Notice	Casing Repair	New Construction	Recomplete	Other	
	Change Plans	X Plug and Abandon	Temporarily Abandon		
	Convert to Injection	Plug Back	Water Disposal		
NOTIFY BLM 24 HOURS 1. MIRU WSU; ND wellf 2. RU WL to run gauge r 3. Tally tbg & TIH open of the clean out tubing. 4. Move tbg to 5187'. Lost leave a plug across the Note to the series of the se	ing & to set CIBP @ 8887 ended to 7037'. Load hole AG ad hole w/ plugging mud & Wolfcamp top. TAG squeeze holes @ 3187' & ent on top of retainer. Revet, reset plug if necessary. squeeze holes @ 1776' & ent on top of retainer. Revet; reset plug if necessary. squeeze holes @ 908' & sof retainer. Reverse circ of retainer. Reverse circ of retainer.	y equipment - no casing a cap w/ 35' cement. The w/ plugging mud & spot 25 sk plug from 49 set a retainer @ 3087'. There is circ tog clean & PO this will leave a 100' efficient & POH. If no retain. This will leave a 100' efficient & POH. If no retain.		en Morrow perfs. I 5 stds & reverse concirc to clean out tbg squeeze w/ 35 sx. Pulloce cement to 100' at the concept of the co	This will ull out of ever top perforation. ull out of ever top perforation. out of retainer &
Name (Printed/Typed) Donna Clack Signature	GENERAL RE	QUIREMENTS A PULATIONS ATT	ACH Date 11-19-03 PERAL OR STATE OFFICE USE	PLIANCE	The next page
Approved by (O	RIG. SÇD.), MEXIS	C. SWOBODA	Title PETROLEUM I		DateNOV 2 5 200.
Conditions of approval, if any, a applicant to conduct operations	are attached. Approval of this notice thereon.	e does not warrant or certify that	Office		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious

or fraudulent statements or representations as to any matter within its jurisdiction.

Form 3160-5 (August 1999)

YATES PETROLEUM CORPORATION OAKASON NV FEDERAL #1 Sec 27-19S-24E EDDY COUNTY, NM

CONTINUED:

8. RU WL & perforate 6 squeeze holes @ 260'. Tie onto 5.5" casing & establish circ back up the 5.5" x 8.625" annulus. Pump 90 sx Class C cement; this should circ cement from 260' to surface - do not displace cement. WOC 24 hrs & tag; reset if necessary. 9. Remove all surface equipment & weld dry hole marker per regulations.

Donna Clack



