

Submit 3 Copies To Appropriate District Office
District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Ave, Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

APR 21 2009

Form C-103
June 19, 2008

LM

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. 30-015-32958
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Marbob Energy Corporation		6. State Oil & Gas Lease No. V-5391
3. Address of Operator PO Box 227, Artesia, NM 88211-0227		7. Lease Name or Unit Agreement Name Coinflip State
4. Well Location Unit Letter D : 990 feet from the North line and 660 feet from the West line Section 18 Township 20S Range 30E NMPM Eddy County		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3312' GR		9. OGRID Number 14049
		10. Pool name or Wildcat Burton Flat, Strawn East

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER. Recompletion ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Recompleted in the Strawn zone as follows:

3/5/09 - MIRU WSU.

3/9/09 - Acdz Atoka perfs @ 11264' - 11271' w/ 500 gal NE Fe 7 1/2% Morrow acid.

3/10/09 - Set CIBP @ 11225'. Atoka zone abandoned. Perf the Strawn @ 10760' - 11025' (20 shots). Dump 35' cmt on CIBP.

3/11/09 - Acdz Strawn perfs w/ 3000 gal NE Fe 15% HCl acid.

3/12/09 - RIH w/ 329 jts 2 3/8" L80 tbg & set @ 10686'. Set pkr @ 10667'.

3/13/09 - RDMO WSU. Producing interval: Strawn 10760' - 11025'.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Diana J. Briggs TITLE Production Manager DATE 4/20/09

Type or print name Diana J. Briggs E-mail address: production@marbob.com PHONE: (575) 748-3303

For State Use Only

APPROVED BY: Acqui TITLE Geologist DATE 4/24/09

Conditions of Approval (if any):