Form 3160-5 (August 1999)

(This space for Federal or State Office use)

Conditions of approval, if any:

Approved by

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APROVED OMB NO. 1004-0135

EXPIRES: NOVEMBER 30, 2000 SUNDRY NOTICES AND REPORTS ON WELLS Lease Serial No. NMNM-77046 Do not use this form for proposals to drill or to re-enter an MAY 12 2009 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals SUBMIT IN TRIPLICATE 7. Unit or CA Agreement Name and No. 1a. Type of Well Oil Well ✓ Gas Well Other 8 Well Name and No. North Pure Gold 8 Federal 10 Name of Operator **DEVON ENERGY PRODUCTION COMPANY, LP** 9. API Well No. 3. Address and Telephone No. 30-015-34594 20 North Broadway, , Oklahoma City, OK 73102 405-235-3611 10. Field and Pool, or Exploratory 4. Location of Well (Report location clearly and in accordance with Federal requirements)* Los Medanos; Upper Penn Shale H SEC 8 T23S R31E 12. County or Parish 13. State NM Eddv CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off ☐ Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity ✓ Other Workover ✓ Subsequent Report Casing Repair New Construction Recomplete Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Plug Back Water Disposal Convert to Injection Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof | If the proposal deepen directionally or recomplete honzontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations of the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection) 4/2/09 - 4/27/09 ND WH. NU BOP. POOH w/tbg & pkr. Pull tbg & pkr. CHC. Pump 10 ppg brine to kill well. POOH w/ 4 stands. Shut blind rams in. MIRU/WL. RIH w/ gauge ring to 12,827' & tag up. POOH w/ gauge ring. RIH w/ BHA. Bled csg dn. Ran pkr w/ plug in place on WL and set @ 12,600' (60' above top perf). EOT @ 12,610'. MIRU coil tbg and CO to 12,969' PBTD. RIse all equipment. TOP. ACCEPTED FOR RECORD MAY 1 0 2009 BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE 14. I hereby certify that the foregoing is true and correct Name Judy A. Barnett x8699 Signed Title Regulatory Analyst 5/4/2009 Date

Date

within its jurisdiction

Title