

Submit One Copy To Appropriate District Office	State of New Me Energy, Minerals and Natu		Form C-103 March 18, 2009
District I 1625 N French Dr , Hobbs, NM 88240	Energy, Minerals and Natu	irai Nesources	WELL API NO. 30-015-22398
<u>District II</u> 1301 W Grand Ave , Artesia, NM 88210 District III	OIL CONSERVATION		5. Indicate Type of Lease
1000 Rio Brazos Rd, Aztec, NM 87410 District IV	1220 South St. Fran Santa Fe, NM 87		STATE X FEE
1220 S St Francis Dr , Santa Fe, NM			6. State Oil & Gas Lease No. SRMA1216
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)			Big Eddy Unit
1. Type of Well: XXOil Well Gas Well Other		8. Well Number 60	
2. Name of Operator BOPCO, L.P.	,		9. OGRID Number 25 (260737
3. Address of Operator P.O. Box 2760 Mic	dland, TX 79702-2760		10. Pool name or Wildcat Fenton (Bone Spring)
4. Well Location			
Unit Letter <u>J</u> : 1980 feet from the Southline and 1980 feet from the East line  Section 20 Township 21S Range 28E NMPM County Eddy			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3204.3 GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INT			SEQUENT REPORT OF:
' PERFORM REMEDIAL WORK ☐       PLUG AND ABANDON ☐       REMEDIAL WORK ☐       ALTERING CASING ☐         TEMPORARILY ABANDON ☐       CHANGE PLANS ☐       COMMENCE DRILLING OPNS.☐       P AND A			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB
OTHER.			eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)			
All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE MAR	TITLE A	livision Pro	od. Supt_ DATE 4/28/09
C 1 (CZ 127)			
For State Use Only			
APPROVED BY	TITLE &	X10	P DATE 5/7/09
Conditions of Approval (if any):			Nelleuse //