State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

to Appropriate
District Office

| | VATION DIVISION | |
|---|------------------------------------|---|
| 1625 N. French Drive, Hobbs, NM 88240 2040 Sol RECEIVED anta Fe, Ne | uth Pacheco w Mexico 87505 | WELL API NO. 30-015-20899 |
| DISTRICT II 1301 Grand, Artesia, NM 88210 DEC 2.3 7003 | | 5. Indicate Type of Lease STATE X FEE |
| DISTRICT III | | 6. State Oil & Gas Lease No. |
| 1000 Rio Brazos Rd., Aztec, NM ACD-ARTESIA | | E-5229 |
| SUNDRY NOTICES AND REPORTS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEI DIFFERENT RESERVOIR. USE "APPLICATION I (FORM C-101) FOR SUCH PROPOSAL | EPEN OR PLUG BACK TO A FOR PERMIT" | 7. Lease Name or Unit Agreement Name |
| I. Type of Well: OIL GAS WELL X WELL OTHER | | Forty Niner Ridge Unit |
| 2. Name of Operator STRATA PRODUCTION COM | PANY | 8. Well No. #1 |
| 3. Address of Operator P.O. BOX 1030, ROSWELL, NEW MEX | ICO 88202-1030 | 9. Pool Name or Wildcat Forty Niner Ridge Delaware |
| 4. Well Location | 100 00202-1000 | 1 Orty Whiel Huge Delaware |
| Unit Letter J: 1980' Feet From The SO | outh Line and 1 | 980 Feet From The East Line |
| Section 16 Township 23 South | Range 30 E | East NMPM Eddy County |
| 10. Elevation (Show wh | ether DF, RKB, RT, GR, etc.) | |
| 11. Check Appropriate Box to I NOTICE OF INTENTION TO: | i i | e, Report, or Other Data SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK PLUG AND ABANDON P | REMEDIAL WORK | ALTERING CASING |
| TEMPORARILY ABANDON CHANGE PLANS | COMMENCE DRILLI | ING OPNS. PLUG AND ABANDONMENT |
| PULL OR ALTER CASING | CASING TEST AND C | CEMENT JOB |
| OTHER: | OTHER: SWE |) - Re-entry x |
| Describe Proposed or Completed Operations (Clearly state all pertinent SEE RULE 1103 | details, and give pertinent dates, | including estimated date of starting any proposed work) |
| 03/17/03: RU Conquest. NUBOP. Set in to clean out. SISD. | pipe racks. Delive | er workstring. PU tools and prep |
| 03/18/03: TIH w/workstring. Tag up at 42 clean. Lay down swivel. TIH w | | |
| 03/18/03: Circ and drlg cement and rock. | Make 94'. SISD. | |
| 03/20/03: Start drlg. RD for repair. | | |
| 03/25/03: Commence drlg. Clean out to | 6460'. TOH w/tools | s. RD swivel. |
| 03/26/03: TIH w/workstring. Tag up oper down workstring. SISD. | n-ended at 6460'. C | Circ hole w/2% KCL. TOH and lay |
| 03/27/03: Move out workstring. MI 2-7/8" and leave hanging. SISD. | plastic coated pipe | e. PU 9-5/8" plastic coated pkr. T |
| 03/28/03: RU and circ pkr fluid to surface 700#) for 15 minutes. Test oka | | |
| , | | |
| | | |
| | | |
| I hereby certify that the information above is true and complete to the best of my | knowledge and belief. | |
| SIGNATURE KULLIN Britt TITLE | Production Reco | rds DATE 12/22/03 |
| TYPE OR PRINT NAME Kelly, M. Britt | @0.00 0 × | TELEPHONE NO. 505-622-1127 Ext 15 |
| (This space for State Use) | | |
| APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY: | | DATE DEC 2.8 |