

SEP 14 2009

Submit 3 Copies To Appropriate District Office
 District I
 1625 N French Dr., Hobbs, NM 88240
 District II
 1301 W Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised May 08, 2003

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well. Oil Well ☐ Gas Well ☐ Other ☐		WELL API NO. <u>30-005-60353</u> 5. Indicate Type of Lease STATE ☒ FEE ☐ 6. State Oil & Gas Lease No.
2. Name of Operator <u>M.E.W. Enterprise</u>		7. Lease Name or Unit Agreement Name <u>State 27</u> 8. Well Number <u>1</u>
3. Address of Operator <u>PO Box 39 Roswell, NM 88202</u>		9. OGRID Number <u>160190</u> 10. Pool name or Wildcat <u>Newmill Strawn South</u>
4. Well Location Unit Letter <u>m</u> : <u>660</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>West</u> line Section <u>27</u> Township <u>4S</u> Range <u>27E</u> NMPM County <u>Chaves</u>		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>GL 3942</u>		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion

* 35' cmt on top
 CSG 1400' 8 5/8 cmt 585sx, 1 inch to circ, 5 1/2 @ 6521 300sx PBD 6375' pre 4218-68,
 set cmt 8' @ 6160', circ mud, cut csg apx 4500', place 100' cmt plug 50' above TAG
 50' Below cut, 100' cmt plug @ 1350'-1250', 150' plug @ 1450'-1300' 50'
 Above 100' Below 8 5/8 csg, 10sx plug @ surface w/ Dry hole marker
 Tag 35' cmt on Top CTRP
 Tag all CSG + Shoe Plugs

Notify OCD 24 hrs. prior
 To any work done.

* No More Than 3000' cmt plugs (Between) casing holes

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Russell Whited TITLE Pres DATE 9-14-09

Type or print name Russell Whited

Telephone No. 505-627-2065

(This space for State use)

APPROVED BY [Signature] TITLE Approval Granted providing work DATE 9/25/09
 Conditions of approval, if any: is complete by 12/25/09