RECEIVED

DEC 1 & 2000

Office Submit 3 Copies 10 Appropriate District	State of New Mexico	DEC 1 0 2009	Form C-103
Office District I 1625 N French Dr , Hobbs, NM 88240 District II	State of New Mexico argy, Minerals and Natural Resource	NMOCELIAR THESIA	Јиле 19, 2008
District II	() L'CONSERVATION DIVISIO		1
	1220 South St. Francis Dr.	5. Indicate Type of L	
District III 1000 Rio Brazos Rd , Aztec, MOBBSOCD	Santa Fe, NM 87505	6. State Oil & Gas L	FEE
1220 S St. Francis Dr , Santa Fe, NM	Santa 1 6, 1414 67505		
87505		V0-6852 & V	
SUNDRY NOTICES ANI (DO NOT USE THIS FORM FOR PROPOSALS TO D		7. Lease Name or Ur	iit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FO		SEGREST STA	TE COM
PROPOSALS) 1. Type of Well: Oil Well Gas Well	Other	8. Well Number]
2. Name of Operator PURVIS OPERATING CO.		9. OGRID Number	131559
3. Address of Operator		10. Pool name or Wi	ldcat
P.O. BOX 51990, MIDLAN	D, TX 79710-1990	WILDCAT LIT	rle box canyon
4. Well Location			
	feet from theNORTH . line a		e <u>EAST</u> line
Section 2	Township 21S Range 21		ounty NM
11. Ele	vation (Show whether DR, RKB, RT, (4549GR	iR, etc.)	
		· .	
12. Check Appropri	ate Box to Indicate Nature of N	otice, Report or Other Da	ta
NOTICE OF INTENTION	ON TO:	SUBSEQUENT REPO	RT OF:
	AND ABANDON 🔲 REMEDIA		TERING CASING
	1		AND A
PULL OR ALTER CASING MULTIF	PLE COMPL CASING/C	EMENT JOB	
DOWN IOLE COMMINGEL			
OTHER:	☐ OTHER:		
13. Describe proposed or completed oper of starting any proposed work). SEE			
or recompletion.	ROLE 1103. For Muniple Complete	ons. Attach wendore diagram (or proposed completion
1			
		,	
12/2/09 - DRILLED	2' - TD = 54'.		
Spud Date:	Rig Release Date:		
I hereby certify that the information above is t	rue and complete to the best of my kn	owledge and belief.	
SIGNATURE SIGNATURE	TITLE LAND MANA	GER DATE	12/8/09
	7 - 20	ourri gon gom ===	. 422 602 7246
Type or print name D. BRIGGS DON	ALDSONE-mail address: land@	ourarsob.com bHON	E: 432-682-/346
For State Use Only			_
APPROVED BY:	TITLE GOOLOG	DATE	19117109
Conditions of Approval (if any):			

ods Out Roots Sump Out Pu	s Ins In
Casing Perf-or-OH Paubing Out Tools Out Roots Out Sump Out Purpose Perfor-OH Paubing Out Roots Out Sump Out Purpose Perfor-OH Roots Out Sump Out Purpose Perfor-OH Paubing Out Sump Out Sump Out Purpose Perfor-OH Paubing Out Roots Out Sump	s In s In p In OF WORK 1-1-12/2/09 Leep
Description Description Drilled to 54 ft,	s In s In In In OF WORK ATIL 12/2/09 Leep
Description Description Drilled to 54 ft,	s In s In In In OF WORK ATIL 12/2/09 Leep
DESCRIPTION 11/12/09 U Drilled to 54 ft,	s In
DESCRIPTION 11 /12 /09 U Drilled to 54 ft,	DF WORK 1-12/2/09 Leep
DESCRIPTION 11/12/09 U Drilled to 54 ft;	1712 12/2/09 deep
Drilled to 54 ft.	deep
	·