

Submit 3 Copies To Appropriate District Office  
District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Ave, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-25383
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name GJ West Coop Unit
8. Well Number 69
9. OGRID Number 229137
10. Pool name or Wildcat 97558 GJ; 7RVS-QN-GB-Glorieta-Yeso

RECEIVED  
APR - 1 2010  
NMOCD ARTESIA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
COG Operating LLC

3. Address of Operator  
550 W. Texas Ave., Suite 1300 Midland, TX 79701

Well Location

Unit Letter P : 25 feet from the South line and 990 feet from the East line  
Section 21 Township 17S Range 29E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3560' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water

Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: Deepen ☒ OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached procedure

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE C Jackson TITLE Agent for COG DATE 3/31/10

Type or print name Kanicia Carrillo E-mail address: cjackson@conchoresources.com Telephone No. 432-686-3087

For State Use Only

APPROVED BY: [Signature] TITLE Geologist DATE 4/7/2010

Conditions of Approval (if any):

COG Operating, LLC  
GJ West Coop Unit #69  
API# 30-015-25383  
P-21-17S-29E  
25' FSL & 990' FEL  
Eddy Co, NM

Deepening Procedure

1. MIRU rig.
2. PU 4-3/4" bit and drill 4-3/4" from 4335' to 5600'.
3. POOH w/ bit and drillstring.
4. RIH w/ logs and log from TD to 4400'.
5. RIH w/ 4", 11.3# casing.
6. Cement casing from TD to 4200' w/ 115 sxs Class C cmt.
7. RDMO rig.

Completion Procedure

1. MIRU rig.
2. RIH/ w/ perforating guns and perforate Yeso from 5500 – 5300 w/ 2 spf, 30 holes.
3. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 190,000 # of sand. Set plug at 5250'.
4. RIH w/ perforating guns and perforate Yeso from 5200' – 5000'.
5. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 190,000 # of sand. Set plug at 4950'.
6. RIH w/ perforating guns and perforate Yeso from 4900' – 4700'.
7. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 190,000 # of sand.
8. RIH and drill out plug at 4950' and 5250'.
9. RIH and cut 4" casing at 4200'. POOH w/ 4" casing. Leave 4" liner from 4200' to 5600' (TD).
10. RIH w/ tbg and locate end of tbg at 4100'.
11. RIH w/ rods and pump.
12. RDMO rig.