Submit 3 Copies to Appropriate

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs NM 88240 WELL API NO. 2040 South Pacheco 30-015-01470 DISTRICT II 811 South First, Artesia, NM 88210 Santa Fe, New Mexico 87505 5. Indicate Type of Lease STATE 🛛 FEE **DISTRICT III** 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd, Aztec, NM 87410 B-3149 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS). 1. Type Of Well: OIL × RECEIVED Red Lake Sand Unit OTHER 8. Well No. 2. Name of Operator JAN 2 6 2004 Mack Energy Corporation 28 9. Pool name or Wildcat 3. Address of Operator OCD-ARTESIA Red Lake; Queen-Grayburg-SA P.O. Box 960, Artesia, NM 88211-0960 4. Well Location South \_ Feet From The Feet From The Line and Line Range 28E Eddy NMPM County Section Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ALTERING CASING PLUG AND ABANDON REMEDIAL WORK **TEMPORARILY ABANDON** PLUG AND ABANDONMENT CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Mack Energy Corporation proposes to plug and abandon well as follows: 1. Notify OCD 24 hours prior to starting plugging operations. 2. Set 100' cement plug from 1721-1621'. WOC and tag. 3. Circulate hole with mud gel. 203'
4. Perforate @ 563' squeeze 100' cement 50' cement 5. Perforate @ 250' squeeze 100' cement back to 150'. - Both Strings 6. Perforate @ 60' circulate cement to surface. - Both strings - woc 24 HPS- TAG 7. Install dry hole marker. **Production Clerk** 1/26/2004 DATE -TYPE OR PRINT NAME TELEPHONE NO Jerry W. Sherrell (This space for State Use) JAN 28 21

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY-

## MACK ENERGY CORPORATION RED LAKE SAND UNIT #28 Sec 20 T17S R28E 2310FSL 330FEL

'8 5/8"-28#
8 5/8"-28# Set @ 513' w/50sks
7" 20# @ 1671' C/w 50sks
OPEN HOLE 1670'-1971'

- 1. Notify OCD 24 hrs. prior to any work done.
- 2.Set 100' cmt plug 1721-1621' and tag.
- 3.Circ hole with mud gel.
- 4.Perf @ 563' squeeze 100' cmt plug 50' above & below 8 5/8" and tag.
- 5. Perf @ 250' squeeze 100' cmt plug back to 150'
- 6. Perf @ 60' circ cmt to surface
- 7. Install Dry Hole Marker