

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO. 30-015-01485
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-8435

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).	
1. Type Of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	RECEIVED
2. Name of Operator Mack Energy Corporation	JAN 26 2004
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960	OCD-ARTESIA
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>20</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	7. Lease Name or Unit Agreement Name Red Lake Sand Unit
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	8. Well No. 21
	9. Pool name or Wildcat Red Lake; Queen-Grayburg-SA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Mack Energy Corporation proposes to plug and abandon well as follows:

1. Notify OCD 24 hours prior to starting plugging operations.
2. Set 35 sx cement @ 1782', 100' above perforations. WOC and tag.
3. Circulate hole with mud gel.
4. Perforate @ 60' circulate cement to surface. — WOC - 24 HRS - TAG
5. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 1/24/04
TYPE OR PRINT NAME Jerry W. Sherrell TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature] TITLE Wild Sep ID DATE JAN 28 2004
CONDITIONS OF APPROVAL, IF ANY:

MACK ENERGY CORPORATION
RED LAKE SAND UNIT #21
Sec 20 T17S R28E 990FSL 2310FEL

1. Notify OCD 24 hrs. prior to any work done.
2. Set cmt plug above perfs @ 1782' 35sks and tag
3. Circ hole with mud gel.
4. Perf @ 60' circ cmt to surface
5. Install Dry Hole Marker

PERFS 1882-1906'

8 5/8"-28# Set @ 2100' cmt 1000sks & Circ