Form 3160-5 (June 1990)

OCA

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

JAN 9 9 2004

FORM APPROVED
Budget Bureau No. 1004-0135

Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Designation and Serial No.
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT -" for such proposals		6. If Indian, Alottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well: OIL GAS WELL OTHER 2. Name of Operator		8. Well Name and Number LENTINI "1" FEDERAL
CHEVRON USA INC		3
3. Address and Telephone No. 15 SMITH ROAD, MIDLAND, TX 79705 915-687-737		9. API Well No. 30-015-27535
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, Exploaratory Area
Unit Letter E: 1825' Feet From The NORT Line and 900' Feet From The		HERRADURA BEND; DELAWARE, EAST
WEST Line Section 1	Township 23-S Range 28-E	11. County or Parish, State EDDY, NM
12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data		
TYPE OF SUBMISSION TYPE OF ACTION		
Notice of Intent✓ Subsequent Report☐ Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Atlering Casing ✓ OTHER: ADD PAY & FRAC ST	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)
directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work,)*. 12-09-03: MIRU KEY #314. 12-10-03: RU HOT OIL UNIT. PUMP 75 BBLS HOT WTR DN TBG W/CHEMICALS. 12-11-03: TIH W/CIBP & SET @ 6220'. TIH W/PERF GUN. UNABLE TO GET BELOW 5300'. 12-12-03: TIH W/TBG TO 6200. PERF 6236-44,6066-80,5957-76,5878-5899,5866-74. 12-15-03: PU RBP & PKR. 12-16-03: ACIDIZE DELAWARE PERFS 5870-6080 W/9800 GALS 15% HCL, 6136-6164 W/2400 GALS ACID,6039-6080 W/1800 GALS ACID, 5957-5976 W/1900 GALS ACID,5866-5899 W/1500 GALS,5570-5582 W/1000 GALS ACID. REL PKR & RBP. 12-17-03: PU CIBP & TIH TO 6100. SET CIBP @ 6100. SET PKR. 12-18-03: WAIT ON FRAC CREW. 12-22-03: FRAC PERFS 6039-6080 W/17,000 GALS 30# X-LINK GEL. FLUSH TO PKR. 12-23-03: FREE POINT TBG. STUCK @ 5560. FREE @ 5550. BACK OFF TBG @ 5534. TIH W/WASH PIPE TO 5195. 12-24-03: TAG @ 5548. WASH OVER TBG TO 5728. 12-29-03: TIH W/OVERSHOT. FREE POINT TBG. FREE @ 5875. CUB TBG @ 5875. 12-30-03: RIG REPAIRS. 12-31-03: WORK TBG FREE. PU SHOE, WP, & TBG TO 5510. 1-02-04: TAG TOF @ 5875. WASH OVER FISH FR 5920-6016. TAG PKR @ 6016. 1-05-04: TAG TOF @ 5875. LATCH FSH. REL PKR. 1-08-04: SET CIBP @ 5910. TIH TO 5793. SET PKR @ 5793. 1-08-04: FRAC PERFS 5866-99 W/17,500 GALS YF130ST GET & SAND. FLUSH TO PKR. 1-09-04: REL PKR. TAG SAND @ 5893. PUH TO 5490. 1-12-04: DRILL CIBP @ 5910. C/O TO 6087. PUH TO 5730. 1-13-04: TAG @ 6087. C/O SAND FR 6087-6100. DO CIBP @ 65100. TAG @ 6147. C/O SD TO 6252. 1-14-03: PU SN, TBG & TAC. TIH W/2 7/8" PROD TBG. TAC @ 5820. SN @ 6200. EOT @ 6237. PU 2 1/2"X1 3/4"X20" PMP. TIH W/RDS. 1-15-03: HANG WELL ON. LOAD & TEST TBG. RIG DOWN. CLEAN LOCATION. RELEASE RIG. FINAL REPORT. TURN OVER TO PRODUCTION.		
14. I hereby certify that the longoing is true and correct SIGNATURE SIGNATURE TYPE OR PRINT NAME Denise	TITLE Regulatory Specialist Leake	DATE 1/22/2004
(This space for Federal or State office use)		
APPROVED CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.