OCD-ARTESIA

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NM 93772

SUNDRY NOTICES AND REPORTS ON WELLS

Form 3160-5 (April 2004) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				FORM APPROVED OM B No 1004-0137 Expires March 31, 2007 5 Lease Serial No. NM 93772 6 If Indian, Allottee or Tribe Name	RM ENEL 2010
SUBMIT IN TR	IPLICATE- Other instr	7. If Unit or CA/Agreement, Name and/or No	Un/		
1 Type of Well ✓ Oil Well 2. Name of Operator Merit Energy	Gas Well Other			8. Well Name and No. Shugart West 19 Federal #4 9 API Well No	₹/
3a Address 13727 Noel Rd. Suite 500 Dallas, Texas 75240		3b Phone No (include area code) 972-628-1569		30-015-30647 10 Field and Pool, or Exploratory Area	
4 Location of Well (Footage, Sec., T, R, M, or Survey Description) 660' FSL & 660' FWL Sec. 19-T18S-R31E			Shugart; Bone Springs North 11 County or Parish, State Eddy Co., New Mexico	1	
12. CHECK AI	PPROPRIATE BOX(ES) TO	INDICATE NATURI	E OF NOTICE, RE	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION		TYP			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Star Reclamation Recomplete Temporarily Aba Water Disposal	Well Integrity Other Add perfs	

- 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)
 - 1. MIRU WSU. ND WH. NU BOP's & test. RU tbg. tools. Kill will if needed w/2% KCL. POOH w/rods, pump & tbg.
 - 2. RIH w/bit & scraper to PBTD. POOH. Clean-out fill if needed.
 - 3. RU EL & PU perf gun loaded 3 spf. Assemble to include GR/CCL tools. Log gun on depth & perf Bone Springs 8215-8291' MD. Tie-in using log. Leave well SI while perforating. POOH w/guns. RD EL.
 - 4. MIRU pumping services.
 - 5. RIH w/tbg. plug & pkr. Set plug below new perfs. Set pkr above new perfs. Pump 8000 gals 15% HCL w/diverter. Flush w/2% KCL. Move up hole & isolate old perfs only (8175' - 8204') & give them 2500 gals acid wash. RD pumping services. Swab back acid.
 - 6. Unseat pkr. Retrieve plug & POOH.
 - 7. RIH w/production tbg., rods & pump and hang-off. RDMO WSU. Place well on production and obtain test.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14 Thereby certify that the foregoing is true and correct Name (Printed/Typed)								
Lynne Moon		Title Regulatory Manager						
Signature noon	Date	05/03	/2010	APPROVED				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by	Title			Date MAY 2 8 2010				
Conditions of approval, if any, are attached Approval of this notice does not warrar certify that the applicant holds legal or equitable title to those rights in the subject lead which would entitle the applicant to conduct operations thereon	ase Office		Bl	JS/ Chris Walls JREAU OF LAND MANAGEMENT				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction								

West Shugart 19 Federal 4 30-015-30647 Merit Energy Company May 26, 2010 Conditions of Approval

- 1. Surface disturbance beyond the existing pad must have prior approval.
- 2. Closed loop system required.
- 3. A minimum of a 3M BOP is required and must be tested prior to performing operations. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 4. Operator to have H2S monitoring equipment on location as H2S has been reported from wells in the area.
- 5. Subsequent sundry with well test and wellbore schematic required.

CRW 052610