

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
301 W. Grand Avenue, Artesia, NM 88210  
District III  
1050 Rio Brazos Road, Aztec, NM 87417  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

MAY 03 2010

NMOC D ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-00644

### Release Notification and Corrective Action

NSEB/009836860

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Fairway Resources	Contact	Matt Eagleston
Address	538 Silicon Drive Suite 101, Southlake, TX 76902	Telephone No.	(817) 416-1946
Facility Name	South Red Lake II Unit 31	Facility Type	Well Location
Surface Owner	BLM	Mineral Owner	BLM
		Lease No.	LC-028755A

#### LOCATION OF RELEASE

Unit Letter "N"	Section 35	Township 17S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
--------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude North Longitude West

#### NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	Unknown	Volume Recovered	0 bbl
Source of Release	Flow Line	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	
Was Immediate Notice Given?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully \*

Describe Cause of Problem and Remedial Action Taken. Flow line failed causing an unknown volume of produced water to be released. During initial response activities the flow line was clamped and soil was excavated.  
Describe Area Affected and Cleanup Action Taken. Site was excavated, confirmation soil samples were collected from the excavation, impacted soil was transported to Lea Land, LLC for disposal, non-impacted soil was purchased locally and the excavation was backfilled. Please see attached Basin Environmental Consulting Remediation Summary and Site Closure Request, dated April 2010, for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature	<i>John J. Pulte</i>	Approved By	<i>M. L. Brannon</i>
Printed Name:	John J. Pulte	Approval Date	JUN 07 2010
Title	Operation Engineer	Expiration Date	N/A
E-mail Address:	j.pulte@fairwayresources.com	Conditions of Approval	
Date 4/06/2010	Phone 817-416-1946		

2RP-416