

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

**DO NOT use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

SUBMIT IN TRIPLICATE - Other instructions on page 2.

## 1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator  
Devon Energy Production Co., LP3a. Address  
20 North Broadway  
OKC, OK 731023b. Phone No (include area code)  
(405)-552-78024. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Sec 29-T16S-R28E  
SL- 2310' FNL & 330' FEL BHL 2340' FNL & 4889' FEL

5. Lease Serial No.

NM-54648

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No

8. Well Name and No  
Dickens 29 Federal 3H9. API Well No.  
30-015-3722010. Field and Pool or Exploratory Area  
Dog Canyon; Wolfcamp11. Country or Parish, State  
Eddy County, NM

## 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Wolfcamp</u>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	<u>Completion Report</u>
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

03/05/2010 - 04/07/2010:

MIRU BJ. Stages 1-6 acidize/frac w/3500 gal 15% NEFE acid, 50,000 gal pad, 95,000 gal snd laden fluid, 23710# total 100 mesh snd, 566,498# 30/50 Ottawa, 102,569# 20/40 Ottawa. Stages 7-10 acid/frac w/13,682 acid, 115,290 gal linear gal pad, 301,277 gal snd laden, 2520 gal flush, 6039# 100 mesh, 151,081# 20/40 Ottawa, 2000 gal linear, 30 bbls x-link flush. RD MO frac equip. Open well, flow bck. Place on rod pmp, turn well over to production.

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)  
Stephanie A. Ysasaga

Title Sr. Staff Engineering Technician

Signature

Date 05/18/2010

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

MAY 29 2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

M2