Subina 1 Copy To Appropriate District Office		of New Me				Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	als and Natu	ls and Natural Resources		NO.	October 13, 2009	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION				30-005-637:		:
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410				5. Indicate Type of Lease STATE FEE		
District IV Santa Fe, NIVI 8/303				6. State Oil	& Gas Lease N	lo.
1220 S. St. Francis Dr., Santa Fe, NM 87505						
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" CORNEL OF SUPERIOR OF S				7. Lease Name or Unit Agreement Name LL&E "B" Federal		
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well ⊠ Other			8. Well Number 5		
2. Name of Operator		JUN 21 2010		9. OGRID Number		
Roswell Operating LLC  3. Address of Operator		NMOCD ARTESIA		10. Pool name or Wildcat		
PO Box 2769, Hobbs, New Mexico 88241		NMOCD ART		West Pecos Slope Abo		
4. Well Location						
	:_840feet	from theSC	OUTH	line and	1980	_feet from the
EASTline Section 1 Tow	rnship 6S R	ongo 22E	NMPM	4 (	COUNTY CHAVE	e e
Section 1 Tow	11. Elevation (Show	ange 22E wwhether DR,			County CHAVE	23
12. Check A	appropriate Box to	Indicate N	ature of Notice,	Report or C	Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK						IG CASING □
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI			
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	. 🛚	CASING/CEMEN	1 JOB		
<del>-</del>			OTHER Comm	4- CIMD		
OTHER:				ert to SWD.		
13. Describe proposed or complete of starting any proposed wo						
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.						
MIRU JWS 5/24/10.						
proposed completion of recompletion.  MIRU JWS 5/24/10.  1] Squeeze Abo perforations [2889'-2907'] w/ 100 sx Class C.[5/25/10]  2] Drill out, test squeeze to 600 psi.[5/26/10]  3] Clean out to PBTD @4395'.[5/27/10 - 5/28/10]  WISTON DATE OF BETU NING.  WISTON DATE OF BETU NING.  WISTON DATE OF BETU NING.						
4]TIH w/ 2-7/8" IPC tubing to 4,186". [Perforations 4,242'- 4,382'] [6/1/10] 5] Circulate hole w/ packer fluid. Acidize w/ 5,000 gallons 15% DINE acid. [6/1/10]						
6] MIT test 350 psi for 30 minutes witnessed by Richard Inge. NMOCD.[6/2/10]						
Spud Date:		Rig Release Da	ite.			
Spau Date.	, i	ds Release De				
I hereby certify that the information a	above is true and com	plete to the be	est of my knowledg	e and belief.		
SIGNATURE SIGNATURE STEPPED DATE 6/7/10						
Type or print name M.Y. Merchant E-mail address:						
_mymerch@penrocoil.comPHONE:575-392-1236						
For State Use Only		^		·,		r 1
APPROVED BY: Vellage // Conditions of Approval (if any):	MedT	TITLE COM	pulanus of	FLEF	DATE 6/	122/10