

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

RECEIVED

SEP 07 2010

NMOCD ARTESIA

5. Lease Serial No.

NM-38474

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Porcupine AAQ Federal 1

9. API Well No.

30-015-25050

10. Field and Pool or Exploratory Area

Square Lake GB SA

11. Country or Parish, State

Eddy NM

1. Type of Well

☒ Oil Well

☐ Gas Well

☐ Other

2. Name of Operator

CBS Operating Corp.

3a. Address P O Box 2236

Midland TX 79702

3b. Phone No. (include area code)

432/685-0878

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FSL & 1750' FWL UL N Sec. 26 T16S R31E

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

7-15-2010 - MI & RU Mayo Marrs. RIH with CIBP to 3662'. POH. RIH with tubing and tag CIBP at 3662'. Circulate plugging mud. Spot 25 sacks cement on top. POH. Spot 25 sacks cement at 1900'. WOC.

7-16-2010 - RIH, no tag. Respot 25 sacks cement at 1900'. WOC. RIH and tag at 1671'. Spot 25 sacks cement at 773'. Perforate at 458'. Spot 25 sacks cement. WOC.

7-20-2010 - RIH and tag at 358'. Perforate at 60'. Circulate 45 sacks cement to surface. Install dry hole marker, clean and level location.

Reclamation Due 1-16-11

Accepted as to plugging of the well bore.
Liability under bond is retained until
Surface restoration is completed.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

M. A. Sirgo, III

Title Engineer

Signature

Date August 23, 2010

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Office

Date

AUG 29 2010

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

Oct