Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District 1	Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr , Hobbs, NM 88240		WELL API NO.
District II 1301 W Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-015-24259 5. Indicate Type of Lease
District III	1220 South St. Francis Dr.	STATE STEE
1000 Rio Brazos Rd, Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr, Santa Fe, NM		B-2071
87505	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	ISALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name of Omit Agreement Name
	CATION FOR PERMIT" (FORM C-101) FOR SUCH	NG Phillips State
PROPOSALS) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number
1. Type of wen. On wen	Gas well Guier	31
2. Name of Operator		9. OGRID Number
	bob Energy Corporation	14049
3. Address of Operator	27, Artesia, NM 88211-0227	10. Pool name or Wildcat Artesia; Queen-Grayburg-San Andres
	27, Attisia, INIVI 60211-0227	Artesia, Queen-Grayburg-San Andres
4. Well Location	1000 0 0 1	
Unit Letter E :	1980feet from theNorth line and	
Section 27	Township 17S Range 28E	NMPM Eddy County
	11. Elevation (Show whether DR, RKB, RT, GR, e	tc.)
En ser	3663' GR	
10 (1)	A companying Day to I disease NI in China	P. A. Odla Da
12. Check A	Appropriate Box to Indicate Nature of Notic	e, Report or Other Data
NOTICE OF IN	ITENTION TO: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WO	
TEMPORARILY ABANDON		PRILLING OPNS. P AND A
PULL OR ALTER CASING	-	_
DOWNHOLE COMMINGLE		
		· ·
	_	
OTHER:		complete-Same Zone (Add Perfs)
13. Describe proposed or comp	pleted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
13. Describe proposed or comp of starting any proposed w	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple (and give pertinent dates, including estimated date
13. Describe proposed or comp	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple (and give pertinent dates, including estimated date
13. Describe proposed or comp of starting any proposed w	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple (and give pertinent dates, including estimated date
13. Describe proposed or comp of starting any proposed we proposed completion or rec	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple (and give pertinent dates, including estimated date
13. Describe proposed or comp of starting any proposed w proposed completion or reconstruction. Recompleted in the Graybu	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple (completion. urg & San Andres zones as follows:	and give pertinent dates, including estimated date
13. Describe proposed or compof starting any proposed we proposed completion or red Recompleted in the Graybu 7/23/10 – MIRU. POOH v	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple (completion. urg & San Andres zones as follows: v/rods & pump. POOH w/tbg.	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
13. Describe proposed or compof starting any proposed we proposed completion or reconstruction. Recompleted in the Graybur 7/23/10 – MIRU. POOH v 7/27/10 – Perf the Graybur	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. arg & San Andres zones as follows: w/rods & pump. POOH w/tbg. g & San Andres zones @ 1941' – 2465' (38 shots).	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of Acdz w/ 1000 gal NE Fe 15% HCl acid.
13. Describe proposed or compof starting any proposed we proposed completion or reconstruction. Recompleted in the Graybut 7/23/10 – MIRU. POOH v 7/27/10 – Perf the Graybut RIH w/ 93 jts 2 3/	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. urg & San Andres zones as follows: v/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). 8" tbg. Set @ 3036'. RIH w/ pump & rods. Hang v	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of Acdz w/ 1000 gal NE Fe 15% HCl acid.
13. Describe proposed or compof starting any proposed we proposed completion or reconstruction. Recompleted in the Graybut 7/23/10 – MIRU. POOH v 7/27/10 – Perf the Graybut RIH w/ 93 jts 2 3/	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. arg & San Andres zones as follows: w/rods & pump. POOH w/tbg. g & San Andres zones @ 1941' – 2465' (38 shots).	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of Acdz w/ 1000 gal NE Fe 15% HCl acid.
13. Describe proposed or compof starting any proposed we proposed completion or reconstruction. Recompleted in the Graybut 7/23/10 – MIRU. POOH v 7/27/10 – Perf the Graybut RIH w/ 93 jts 2 3/	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. urg & San Andres zones as follows: v/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). 8" tbg. Set @ 3036'. RIH w/ pump & rods. Hang v	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of Acdz w/ 1000 gal NE Fe 15% HCl acid.
13. Describe proposed or compof starting any proposed we proposed completion or reconstruction. Recompleted in the Graybut 7/23/10 – MIRU. POOH v 7/27/10 – Perf the Graybut RIH w/ 93 jts 2 3/	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. urg & San Andres zones as follows: v/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). 8" tbg. Set @ 3036'. RIH w/ pump & rods. Hang v	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of Acdz w/ 1000 gal NE Fe 15% HCl acid.
13. Describe proposed or compof starting any proposed we proposed completion or reconstruction. Recompleted in the Graybut 7/23/10 – MIRU. POOH v 7/27/10 – Perf the Graybut RIH w/ 93 jts 2 3/	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. urg & San Andres zones as follows: v/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). 8" tbg. Set @ 3036'. RIH w/ pump & rods. Hang v	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of Acdz w/ 1000 gal NE Fe 15% HCl acid.
13. Describe proposed or compof starting any proposed we proposed completion or reconstruction. Recompleted in the Graybut 7/23/10 – MIRU. POOH v 7/27/10 – Perf the Graybut RIH w/ 93 jts 2 3/	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. urg & San Andres zones as follows: v/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). 8" tbg. Set @ 3036'. RIH w/ pump & rods. Hang v	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of Acdz w/ 1000 gal NE Fe 15% HCl acid.
13. Describe proposed or compof starting any proposed we proposed completion or reconstruction. Recompleted in the Graybut 7/23/10 – MIRU. POOH v 7/27/10 – Perf the Graybut RIH w/ 93 jts 2 3/	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. urg & San Andres zones as follows: v/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). 8" tbg. Set @ 3036'. RIH w/ pump & rods. Hang v	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of Acdz w/ 1000 gal NE Fe 15% HCl acid.
13. Describe proposed or compof starting any proposed we proposed completion or red Recompleted in the Graybut 7/23/10 - MIRU. POOH v 7/27/10 - Perf the Graybut RIH w/ 93 jts 2 3/ Producing Interva	poleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. Targ & San Andres zones as follows: W/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). W/ stag. Set @ 3036'. RIH w/ pump & rods. Hang w/ stag. Grayburg & San Adres @ 1941' – 3169'.	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of Acdz w/ 1000 gal NE Fe 15% HCl acid.
13. Describe proposed or compof starting any proposed we proposed completion or reconstruction. Recompleted in the Graybut 7/23/10 – MIRU. POOH v 7/27/10 – Perf the Graybut RIH w/ 93 jts 2 3/	oleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. urg & San Andres zones as follows: v/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). 8" tbg. Set @ 3036'. RIH w/ pump & rods. Hang v	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of Acdz w/ 1000 gal NE Fe 15% HCl acid.
13. Describe proposed or compof starting any proposed we proposed completion or red Recompleted in the Graybut 7/23/10 - MIRU. POOH v 7/27/10 - Perf the Graybut RIH w/ 93 jts 2 3/ Producing Interva	poleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. Targ & San Andres zones as follows: W/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). W/ stag. Set @ 3036'. RIH w/ pump & rods. Hang w/ stag. Grayburg & San Adres @ 1941' – 3169'.	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of Acdz w/ 1000 gal NE Fe 15% HCl acid.
13. Describe proposed or compof starting any proposed we proposed completion or red Recompleted in the Graybut 7/23/10 — MIRU. POOH v 7/27/10 — Perf the Graybur RIH w/ 93 jts 2 3/ Producing Interval	Poleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. For Mu	Acdz w/ 1000 gal NE Fe 15% HCl acid. vell on pump. RDMO. RECEIVED SEP 2 1 2010 NMOCD ARTESIA
13. Describe proposed or compof starting any proposed we proposed completion or red Recompleted in the Graybut 7/23/10 — MIRU. POOH v 7/27/10 — Perf the Graybur RIH w/ 93 jts 2 3/ Producing Interval	poleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. Targ & San Andres zones as follows: W/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). W/ stag. Set @ 3036'. RIH w/ pump & rods. Hang w/ stag. Grayburg & San Adres @ 1941' – 3169'.	Acdz w/ 1000 gal NE Fe 15% HCl acid. vell on pump. RDMO. RECEIVED SEP 2 1 2010 NMOCD ARTESIA
13. Describe proposed or compof starting any proposed we proposed completion or recomposed completion or recomposed completed in the Graybur 7/23/10 — MIRU. POOH vo 7/27/10 — Perf the Graybur RIH w/ 93 jts 2 3/2 Producing Interval	poleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. arg & San Andres zones as follows: w/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). 8" tbg. Set @ 3036'. RIH w/ pump & rods. Hang wil: Grayburg & San Adres @ 1941' – 3169'. Rig Release Date:	Acdz w/ 1000 gal NE Fe 15% HCl acid. Well on pump. RDMO. RECEIVED SEP 2 1 2010 NMOCD ARTESIA Addge and belief.
13. Describe proposed or compof starting any proposed we proposed completion or red Recompleted in the Graybut 7/23/10 — MIRU. POOH v 7/27/10 — Perf the Graybur RIH w/ 93 jts 2 3/ Producing Interval	poleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. arg & San Andres zones as follows: w/ rods & pump. POOH w/ tbg. g & San Andres zones @ 1941' – 2465' (38 shots). 8" tbg. Set @ 3036'. RIH w/ pump & rods. Hang wil: Grayburg & San Adres @ 1941' – 3169'. Rig Release Date:	Acdz w/ 1000 gal NE Fe 15% HCl acid. vell on pump. RDMO. RECEIVED SEP 2 1 2010 NMOCD ARTESIA
13. Describe proposed or compof starting any proposed we proposed completion or reconstruction of reconstruction of starting any proposed we proposed completion or reconstruction or reconstruction. Recompleted in the Graybur 7/23/10 — MIRU. POOH v 7/27/10 — Perf the Graybur RIH w/ 93 jts 2 3/ Producing Interval. Spud Date: I hereby certify that the information SIGNATURE.	Poleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. For Multiple Complete Complet	Acdz w/ 1000 gal NE Fe 15% HCl acid. Acdz w/ 1000 gal NE Fe 15% HCl acid. Well on pump. RDMO. RECEIVED SEP 2 1 2010 NMOCD ARTESIA dge and belief. DATE 9/20/10
13. Describe proposed or compof starting any proposed we proposed completion or red Recompleted in the Graybut 7/23/10 — MIRU. POOH v 7/27/10 — Perf the Graybut RIH w/ 93 jts 2 3/ Producing Interval Spud Date: I hereby certify that the information SIGNATURE Type or print name Diana Jeta	Poleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. For Multiple Complete Complet	Acdz w/ 1000 gal NE Fe 15% HCl acid. Well on pump. RDMO. RECEIVED SEP 2 1 2010 NMOCD ARTESIA Addge and belief.
13. Describe proposed or compof starting any proposed we proposed completion or reconstruction of reconstruction of starting any proposed we proposed completion or reconstruction or reconstruction. Recompleted in the Graybur 7/23/10 — MIRU. POOH v 7/27/10 — Perf the Graybur RIH w/ 93 jts 2 3/ Producing Interval. Spud Date: I hereby certify that the information SIGNATURE.	Poleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. For multiple Complete Complet	Acdz w/ 1000 gal NE Fe 15% HCl acid. Acdz w/ 1000 gal NE Fe 15% HCl acid. Well on pump. RDMO. RECEIVED SEP 2 1 2010 NMOCD ARTESIA Adge and belief. DATE 9/20/10 arbob.com PHONE: _(575) 748-3303_
13. Describe proposed or compof starting any proposed we proposed completion or red Recompleted in the Graybut 7/23/10 — MIRU. POOH v 7/27/10 — Perf the Graybut RIH w/ 93 jts 2 3/ Producing Interval Spud Date: I hereby certify that the information SIGNATURE Type or print name Diana Jeta	Poleted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. For Multiple Complete Complet	Acdz w/ 1000 gal NE Fe 15% HCl acid. Acdz w/ 1000 gal NE Fe 15% HCl acid. Well on pump. RDMO. RECEIVED SEP 2 1 2010 NMOCD ARTESIA Adge and belief. DATE 9/20/10 arbob.com PHONE: _(575) 748-3303_