Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

PSP Antesta

FORM APPROVED OMB NO. 1004-0135

Expires: November 30, 2000

5. Lease Serial No.

SUNDRY 1	VOTICES	AND	REPORTS	ON	WELLS
----------	---------	-----	---------	----	-------

NMNM0417696

Do not use this form for abandoned well. Use Forr	6. 1	f Indian, Allotte	e or Tribe Name		
SUBMIT IN TRIPLICATE -	7. I	f Unit or CA/Ag	greement, Name and/or No		
1. Type of Well X Oil Well Gas Well Other 2. Name of Operator		S		Well Name and I t Tank 3 f	No. edeval #13
OXY USA Inc.	16696		API Well No.		
3a. Address	3b. Phone No. (include ar		30-015-37908		
P.O. Box 50250, Midland, TX 79710- 4. Location of Well (Footage, Sec., T., R., M., or Survey L SL-770 FSL 1909 FEL SWS	Description) SE(0) Sec	432-685-5717 3 T225 €31	Los		or Exploratory Area aware, West
BHC-350FSL 1660FWL SES	sw(n) ii	<i>دد</i> (ر	11.	County or Paris	sh, State
			Edo	ly	NM NM
12. CHECK APPROPRIATE	BOX(ES) TO INI	DICATE NATURE OF I	NOTICE, REPORT	, OR OTHER	DATA
TYPE OF SUBMISSION		TYI	PE OF ACTION		
X Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injecti		Production (Start Reclamation Recomplete Temporarily Aba Water Disposal	X X In Ca	Water Shut-Off Well Integrity Other <u>Amend</u> termediate/Prod sing & Cementing
13. Describe Proposed or Completed Operation (clearly If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. I testing has been completed. Final Abandonment N determined that the final site is ready for final insper.	lete horizontally, give s formed or provide the If the operation results i Notices shall be filed or	ubsurface locations and mea Bond No. on file with BLM/ n a multiple completion or re	sured and true vertical of BIA. Required subseque completion in a new in	depths of all per- uent reports sha nterval, a Form 3	tinent markers and zones. Il be filed within 30 days 3160-4 shall be filed once

RECEIVED

OCT 05 2010

NMOCD ARTESIA

See attached.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct Name (<i>Printed/Typed</i>)	itle						
David Stewart	Sr. Regulatory Analyst						
Ju Stil	Pate	9/16/10					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by	Title		Date				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	е						
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter with	person knowin	ngly and willfully to make to any de	partment or agency of the Utiled				

PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME: OXY USA Inc. LEASE NO.: NMNM0417696

WELL NAME & NO.: | Lost Tank 3 Federal #18

SURFACE HOLE FOOTAGE: 770' FSL & 1909' FEL Sec 03-22S-31E BOTTOM HOLE FOOTAGE 350' FSL & 1660' FWL Sec 03-22S-31E

LOCATION: | Section 04, T. 22 S., R 31 E., NMPM

COUNTY: | Eddy County, New Mexico

B. CASING

1. The minimum required fill of cement behind the 8-5/8 inch intermediate casing is:

The intermediate should be set in the Fletcher Anyhydrite or Lamar Limestone within 100 to 600 feet below the base of the salt.

□ Cement to surface. If cement does not circulate see B.1.a, c-d above.
 Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to potash.

The DV tool should be placed a minimum of 50 feet below the intermediate casing shoe.

- 2. The minimum required fill of cement behind the 5-1/2 inch production casing is:
 - a. First stage to DV tool, cement shall:
 - Cement to circulate. If cement does not circulate, contact the appropriate BLM office, before proceeding with second stage cement job. Operator should have plans as to how they will achieve circulation on the next stage.
 - b. Second stage above DV tool, cement shall:
 - Cement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with third stage cement job. Operator should have plans as to how they will achieve circulation on the next stage.
 - c. Third stage above DV tool, cement shall:
 - Cement to surface. If cement does not circulate, contact the appropriate BLM office.

RGH 100410