UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Lease Serial No. NMLC028784B

1					
	6	If Indian	Allottee	or Tribe	Name

SUNDRY		NMLC028784B 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. NMNM88525X			
Do not use thi abandoned we					
SUBMIT IN TRI					
Type of Well Gas Well ☐ Oth	Ner	,		8. Well Name and No BURCH KEELY	
2. Name of Operator	Contact: ROB	YN ODOM		9. API Well No.	
	RATION E-Mail: rodom@conchor			30-015-36181	
3a. Address ARTESIA, NM 88211-0227	Ph:	Phone No. (include area co 432-685-4385			IACKSON SR-Q-GRE
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)			11. County or Parish	
Sec 18 T17S R30E SENW 17 32.83719 N Lat, 104.01143 W				EDDY COUNT	TY, NM
12. CHECK APPI	ROPRIATE BOX(ES) TO INC	DICATE NATURE O	F NOTICE, REF	PORT, OR OTH	ER DATA
TYPE OF SUBMISSION		TYPE	OF ACTION		
Notice of Intent	☐ Acidize	Deepen	□ Productio	n (Start/Resume)	□ Water Shut-Off
Subsequent Report	☐ Alter Casing	☐ Fracture Treat	Reclamati		□ Well Integrity
·	□ Casing Repair	New Construction	Recomple	1	Other Change to Original
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and Abandon☐ Plug Back☐			PD
13. Describe Proposed or Completed Op		_	□ Water Dis		
Attach the Bond under which the wo following completion of the involved	ally or recomplete horizontally, give sind will be performed or provide the Boll operations. If the operation results in boundonment Notices shall be filed only final inspection.)	ond No. on file with BLM/ n a multiple completion or	BIA. Required subs recompletion in a ne	equent reports shall winterval, a Form 3	be filed within 30 days 160-4 shall be filed once
COG Operating respectfully re	equests permission to change	the casing program to	D :		
casing 48# J-55/H-40 & ceme system, wt 10, vis 30. Set 8-5 a 7-7/8? hole to 4800' w/ cut t	Phole to 350? w/fresh water ment-w/-350sxs to surf. Drill 11? of /8? intermediate casing 24# Jorine mud system, wt 9.1, vis 2800sxs to surface. Note: On proceeding.	or 12-1/4" hole to 120 55 & cement w/ 500s 9-32-Test_Yeso form	0? w/brine mud xs to surface. Dr ation. Run 5-1/2'	is see H	CEIVED
				NO	OV 04 2010
SEE ATTACH CONDITIONS	HED FOR S OF APPROVAL			NMO	CD ARTESIA
14. Thereby certify that the foregoing is	true and correct. Electronic Submission #9625 For MARBOB ENERGY nmitted to AFMSS for processin	CORPORATION, sen	t to the Carlsbad		
Name (Printed/Typed) ROBYN C	•	· ·	SON RESPONS	•	
Signature (Electronic S	Submission)	Date 10/2	9/2010	!	
	THIS SPACE FOR F	EDERAL OR STAT	E OFFICE US	E	
Approved By CHRISTOPHER WA	ALLS	TitlePETRO	LEUM ENGINE	≣R	Date 11/03/2(
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to cond	uitable title to those rights in the subje		sbad	1	et.
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime statements or representations as to an	e for any person knowingly y matter within its jurisdic	and willfully to mal	ke to any department	or agency of the United

COG Operating LLC Grayburg Jackson; SR-Q-Grbg-SA Use for T-17-S, R-30-E Eddy County, NM

1. Casing Program

	·	OD					
Hole Size	Interval	Casing	Weight	Grade	Jt., Condition	Jt.	brst/clps/ten
17 ½"	0-350'	13 3/8"	48#	H-40orJ-55	ST&C/New	ST&C	9.22/3.943/15.8
11"or12 ¼"	0-1200'	8 5/8"	24or32#	J-55	ST&C/New	ST&C	3.03/2.029/7.82
7 7/8"	0-5100'	5 1/2"	15.5or17#	J-55orL-80	LT&C/New	LT&C	1.88/1.731/2.42

2. Cement Program

13 3/8" Surface Casing:

Class C, 350 sx, yield 1.32, back to surface

8 5/8" Intermediate Casing:

11" Hole:

Single Stage: 50:50:10, 300 sx lead, yield-2.45 + Class C, 200 sx tail, yield-1.32, back to surface.

5 1/2" Production Casing:

Single Stage: 35:65:6, 500 sx Lead, yield-2.05 + 50:50:2, 300 sx Tail, yield-1.37, to 200' minimum tie back to intermediate casing.

CONDITIONS OF APPROVAL

OPERATOR'S NAME: | COG Operating LLC

LEASE NO.: NMLC-028784B

WELL NAME & NO.: | Burch Keely Unit 991

SURFACE HOLE FOOTAGE: 1708' FNL & 2517' FWL

LOCATION: | Section 18, T. 17 S., R 30 E., NMPM

COUNTY: | Eddy County, New Mexico

I. DRILLING

A. DRILLING OPERATIONS REQUIREMENTS

The BLM is to be notified a minimum of 4 hours in advance for a representative to witness:

- a. Spudding well
- b. Setting and/or Cementing of all casing strings
- c. BOPE tests

Eddy County

Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822

- 1. A Hydrogen Sulfide (H2S) Drilling Plan should be activated 500 feet prior to drilling into the Yates formation. As a result, the Hydrogen Sulfide area must meet

 Onshore Order 6 requirements, which includes equipment and personnel/public protection items. If Hydrogen Sulfide is encountered, please provide measured values and formations to the BLM.
- 2. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval. If the drilling rig is removed without approval an Incident of Non-Compliance will be written and will be a "Major" violation.
- 3. The record of the drilling rate along with the GR/N well log run from TD to surface (horizontal well vertical portion of hole) will be submitted to the BLM office as well as all other logs run on the borehole 30 days from completion. If available, a digital copy of the logs is to be submitted in addition to the paper copies. The Rustler top and top and bottom of Salt are to be recorded on the Completion Report.

B. CASING

Changes to the approved APD casing and cement program require submitting a sundry and receiving approval prior to work. Failure to obtain approval prior to work will result in an Incident of Non-Compliance being issued.

Centralizers required on surface casing per Onshore Order 2.III.B.1.f.

Wait on cement (WOC) time prior to drilling out for a primary cement job will be a minimum 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compressive strength, whichever is greater for all casing strings. DURING THIS WOC TIME, NO DRILL PIPE, ETC. SHALL BE RUN IN THE HOLE. Provide compressive strengths including hours to reach required 500 pounds compressive strength prior to cementing each casing string. See individual casing strings for details regarding lead cement slurry requirements.

No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.

Possible lost circulation in the Grayburg and San Andres formations. Possible water flows in the Salado and Artesia Groups

- 1. The 13-3/8 inch surface casing shall be set at approximately 350 feet (a minimum of 25 feet into the Rustler Anhydrite and above the salt) and cemented to the surface.
 - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.
 - b. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry.
 - c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
 - d. If cement falls back, remedial cementing will be done prior to drilling out that string.

- 2. The minimum required fill of cement behind the 8-5/8 inch intermediate casing is:

 Cement to surface. If cement does not circulate see B.1.a, c-d above.
- 3. The minimum required fill of cement behind the 5-1/2 inch production casing is:
 - Cement to surface. If cement does not circulate, contact the appropriate BLM office. Additional cement may be required, as the excess cement calculates to 18%.
- 4. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

C. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **2000 (2M)** psi.
 - a. For surface casing only: If the BOP/BOPE is to be tested against casing, the wait on cement (WOC) time for that casing is to be met (see WOC statement at start of casing section). Independent service company required.
- 3. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
 - a. In a water basin, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. The casing cut-off and BOP installation can be initiated four hours after installing the slips, which will be approximately six hours after bumping the plug. For those casing strings not using slips or where the float does not hold, the minimum wait time before cut-off is eight hours after bumping the plug or when the cement reaches 500 psi compressive strength (including lead when specified), whichever is greater. BOP/BOPE testing can begin after the above conditions are satisfied.

- b. The tests shall be done by an independent service company utilizing a test plug **not** a **cup** or **J-packer**. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (18 hours) or potash (24 hours) prior to initiating the test.
- c. The results of the test shall be reported to the appropriate BLM office.
- d. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- e. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.
- f. Effective November 1, 2008, no variances will be granted on reduced pressure tests on the surface casing and BOP/BOPE. Onshore Order 2 requirements will be in effect.

D. DRILL STEM TEST

If drill stem tests are performed, Onshore Order 2.III.D shall be followed.

E. WASTE MATERIAL AND FLUIDS

All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area.

CRW 110310