Form 3160-5 (August 2007)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

1		OWR	NO.	ıυ	U4-
		Expires	: Ju	ıly	31,
Carial	NI.				

_	Lagra	Serial	Nia
•	Lease	Sellai	INU.
J	RANIRA	04393	

SUNDRY NOTICES AND REPORTS ON N Do not use this form for proposals to drill or to abandoned well. Use Form 3160-3 (APD) for su	o re-enter an	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions of	n page 2.	7. If Unit of CA/Agreement, Name and/or No.
1. Type of Well ☐ Oil Well ☐ Gas Well ☐ Other		8. Well Name and No. DEKALB #A
2. Name of Operator CFM OIL COMPANY, LOUIS FULTON	/	9. API Well No.
3a. Address 3b. Phone No. 575-746-309	y Fic 1702 (include area code) 9 746-4787	10. Field and Pool or Exploratory Area
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)		11. Country or Parish, State
NESW 31 16S 30E NMP	-	EDDY COUNTY NEW MEXICO
12. CHECK THE APPROPRIATE BOX(ES) TO INI	DICATE NATURE OF NOTIC	E, REPORT OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACT	ION
Caring Penair New	ture Treat Recla	mation Water Shut-Off Well Integrity mplete
Subsequent Report Change Plans Plug	and Abandon Temp	orarily Abandon
Final Abandonment Notice Convert to Injection Plug	Back Wate	r Disposal
determined that the site is ready for final inspection.) REQUESTING APPROVAL FOR OFF LEASE MEASUREMENT		RECEIVED DEC 0 9 2010 NMOCD ARTESIA
MISSIAG RAMMED LINFO SFE	ATTACHEN	
14. I hereby certify that the foregoing is true and correct. Name (Printed Typed)		
LOUIS FULTON	Title OWNER	
Signature Alfrica Total	Date 04/30/2008	
THIS SPACE FOR FEDE	RAL OR STATE OFF	ICE USE
Approved by /S/ JD Whitlock Ji Conditions of approval, if any, are attached. Approval of this notice does not warrant or c that the applicant holds legal or equitable title to those rights in the subject lease which we entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any ne	Title L/L-7 ortify uld Office (F.)	Date 1-2/7/100

Bureau of Land Management Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Guidelines for Off-Lease Measurement and Storage.

The following information must be included with any application to store, measure or sale production offlease:

- 1. A formal request (Sundry Notice Form 3160-5) for approval to store, measure or sale production off-lease with an appropriate explanation and diagram(s) describing the proposed operation in detail.
- 2. A map showing the lease numbers and location of all leases and wells that will be sending production off-lease and all measurement points, and/or storage facility. All lease numbers, unitized or communitized areas.
- 3. Any wells or leases proposed to be added to an approved off-lease storage and or measurement facility must be approved by the Authorized Officer prior to their being included in the facility.
- 4. A schematic diagram which clearly identifies and places all equipment that will be utilized.
- 5. Include gas sales meter location and station name or number.