Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD-ARTESIA

FORM APPROVED

| I OIGHT I I I I I I I I I I I I I I I I I I I |
|---|
| OMB No. 1004-0137 |
| Expires: July 31, 2010 |
| |

5. Lease Serial No. NMNM04393

| SUNDRY NOTICES AND REPORTS O Do not use this form for proposals to drill of abandoned well. Use Form 3160-3 (APD) for | or to re-enter an | 6. If Indian, Allottee or Tribe Name |
|---|---|--|
| SUBMIT IN TRIPLICATE - Other instructio | ns on page 2. | 7. If Unit of CA/Agreement, Name and/or No. |
| 1. Type of Well Gas Well Other | | 8. Well Name and No. DEKALB #A |
| 2. Name of Operator CFM OIL COMPANY, LOUIS FULTON | 1 ~ | 9. API Well No. |
| 3a. Address 3b. Phono ARTESIA NM 88211 575-746- | A. Fill Ton No. (include area code) 3099 746-4787 | 10. Field and Pool or Exploratory Area |
| 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) NESW 31 16S 30E NMP | | 11. Country or Parish, State EDDY COUNTY NEW MEXICO |
| 12. CHECK THE APPROPRIATE BOX(ES) TO | INDICATE NATURE OF NOTI | CE, REPORT OR OTHER DATA |
| TYPE OF SUBMISSION | TYPE OF AC | TON |
| Subsequent Report Alter Casing Casing Repair | Fracture Treat Rec. New Construction Rec. | amation (Start/Resume) Water Shut-Off Well Integrity Other porarily Abandon |
| Final Abandonment Notice Convert to Injection | | er Disposal |
| REQUESTING APPROVAL FOR OFF LEASE MEASUREMEN | T | RECEIVED DEC 0 9 2010 NMOCD ARTEGIA |
| M'GCIA LA LIVED SET | ATTAINION | • • |
| 14. I hereby certify that the foregoing is true and correct. Name (Printed Typed) | 111111111111 | |
| LOUIS FULTON | Title OWNER | |
| Signature 1944 | | |
| Signature / Children | Date 04/30/2008 | |
| - fear feller | Date 04/30/2008 DERAL OR STATE OFF | ICE USE |

(Instructions on page 2)

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Bureau of Land Management Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Guidelines for Off-Lease Measurement and Storage.

The following information must be included with any application to store, measure or sale production off-lease:

- 1. A formal request (Sundry Notice Form 3160-5) for approval to store, measure or sale production off-lease with an appropriate explanation and diagram(s) describing the proposed operation in detail.
- 2. A map showing the lease numbers and location of all leases and wells that will be sending production off-lease and all measurement points, and/or storage facility. All lease numbers, unitized or communitized areas.
- 3. Any wells or leases proposed to be added to an approved off-lease storage and or measurement facility must be approved by the Authorized Officer prior to their being included in the facility.
- 4. A schematic diagram which clearly identifies and places all equipment that will be utilized.
- 5. Include gas sales meter location and station name or number.