Submit 1 Copy To Appropriate District Office	State of New Mexico			Form C-103	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			October 13, 2009 WELL API NO.	
District II				30-015-3316	1
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION				Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STAT	
District IV	Santa Fe, NM 87505				& Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM					
87505	ICES AND DEDODITS ON	WEILS		7 Longo No.	ma an Unit Agraamant Nama
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name Grandi	
1. Type of Well: Oil Well Gas Well Other				8. Well Number	
2. Name of Operator Devon Energy Production Company, LP				9. OGRID Number 6137	
3. Address of Operator				10. Pool name or Wildcat	
20 North Broadway, Oklahoma City, OK 73102 405.552.4615				Esperanza; Delaware	
4. Well Location				Lop or anizat, D	
	4. N. d. P 1 666) C . C	/I XX7 / 1*		
	rom the North line and 660				
Section 22 Township 22S Range 27E Eddy County, NM					
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3122 KB; 3103' GL					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐					
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MOLTIPLE COMPL	Ш	CASING/CEMEN	II JOB [_
DOWNHOLE COMMINGLE OTHER:		П	OTHER:		
					Ш
of starting any proposed we	ork). SEE RULE 19.15.7.1	state all 1	pertinent details, and C. For Multiple Co	mpletions: Atta	
proposed completion or rec	ompletion.			Notify	OCD 24 hrs. prior
Proposed Plug & Abandonment				To	any work done.
Proposed Flug & Abandonment					
1. MIRU. POOH w/2-7/8" tul	oing and packer from 5090'	,		4	
			5090'. Top of Bond	e Spring @ 530	4'. Open Delaware Perfs @
3. Circulate wellbore w/9.5# mud @ 5090'.					
4. Spot 60 sx cmt @ 2200'. (Calc. TOC @ 2014'. Top of Delaware @ 2100')					
5. Spot 40 sx cmt @ 500'. Tag TOC @ 400' or shallower. (Calc. TOC @ 376'. 13-3/8" shoe @ 450')					
6. Spot 40 sx cmt from 124' to surface					
7. Cut csg strings off 3' BGL.		MO.			RECEIVED
Spud Date: Rig Release Date:			ite:		FEB 1 4 2011
		_			NMOCD ARTESIA
I hereby certify that the information	above is true and complete	to the be	est of my knowledg	ge and belief.	
<i>(</i>)	Λ 1				
SIGNATURE RAMME Slock TITLE Operations Technician DATE 2-11-11					
Type or print name _Ronnie Slack E-mail address:Ronnie.Slack@dvn.com PHONE: 405.552.4615					
For State Use Only					
APPROVED BY:	When TITLE	Ξ			DATE 2/15/2011
APPROVED BY: TITLE DATE 2/15/2011 Conditions of Approval (if any): Approval Granted providing work is complete by 5/5/2011					
is complete by 5/15/80/1					
			3.7	/	(ENT RED



