Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APROVED OMB NO. 1004-0137 EXPIRES: March 31, 2007

SUNDRY NOTICES AND REPORTS	5. Lease Serial No.			
Do not use this form for proposals to drill or to re-enter an			NMNM-97120	
abandoned well. Use Form 3160-3 (APD) for such proposals SUBMIT IN TRIPLICATE - Other instructions on page 2		6. If Indian, Allottee	or Tribe Name	
1. Type of Well	7. Unit or CA Agree	ement Name and No.		
Oil Well Gas Well Other		8 Well Name and N	lo. 🔥	
2. Name of Operator		eral N Com #1		
DEVON ENERGY PRODUCTION COMPANY, LP		9. API Well No.		
3a, Address 3b. Phone No. (inclu			0-015-23538	
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-4615 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FSL 860' FEL 5 T23S R26E >		10. Field and Pool,	, ,	
			Undesignated Morrow 11. County or Parish, State	
		Eddy	, NM	
12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REP		······································		
TYPE OS SUBMISSION TYPE OF ACTION				
Notice of Intent	Deepen	Production (Start/Resume)	Water Shut-Off	
Alter Casing	Fracture Treat	Reclamation	☐ Well Integrity	
✓ Subsequent Report ☐ Casing Repair ☐ Change Plans		Recomplete Temporarily Abandon	U Other	
Final Abandonment Notice Change Flans Convert to Inj		Water Disposal		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new				
interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)				
PLUG & ABANDONMENT 1. 1/11/11: MIRU. Attempt to POOH w/ packer from 10440'. Unable. Pushed packer down to 10486'. Released on/off tool from packer and TOOH w/2-7/8" tubing. Set CIBP @ 10482'. Tagged CIBP. Spot 35 sx cmt on CIBP. 2. Spot 40 sx cmt from 8137' to 7887'. Tagged. (DV Tool @ 8012') 4. Spot 35 sx cmt from 5125' to 4875'. Tagged. (8-5/8" csg shoe @ 3000') 6. Spot 25 sx cmt from 1925' to 1675'. Tagged. (Delaware top 1800'). 7. Spot 185 sx cmt from 1550' to surface. 8. Cut csg strings off 3' BGL. Set dry hole marker. RDMO. 9. 3/2/11-Wellbore plugged & abandoned PECEVED MAR 1 8 2011 Accepted as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed.				
14. I hereby certify that the foregoing is true and correct Name: Ronnie Slack	Title Operations Techni	cian		
Signature ROMME Stand	Date 3-4-11	ACCEPTED	FOR RECORD	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by	Title	Date MAR	1 5 2011	
Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal cequitable title to those rights in the subject lease which would entitle the applicant to conduct or operations thereon.		XIRFAIL OF L	AND MANAGEMENT O FIELD OFFICE	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

