

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised June 10, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30 005 63263
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Reliance Energy, Inc.		6. State Oil & Gas Lease No. 26232
3. Address of Operator 6 Desta Drive, Suite 5500, Midland, Texas 79705		7. Lease Name or Unit Agreement Name Willow Springs "27" State
4. Well Location Unit Letter <u>L</u> : 1980 feet from the <u>south</u> line and <u>660</u> feet from the <u>west</u> line Section <u>27</u> Township <u>4S</u> Range <u>25E</u> NMPM County <u>Chaves</u>		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3797' GR		9. OGRID Number 149441
		10. Pool name or Wildcat Pecos Slope Abo

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Set CIBP @ 3610', top w/ 35' cmt.

Circ hole w/ 10# mud.

Cut casing @ 3300', pull casing.

Spot plug @ 3350' - 3250', 30 sx. - TAG

Spot plug @ 2000' - 1900', 30 sx. - TAG

Spot plug @ 1025' - 925', 30 sx. - TAG

Spot plug @ 60' - surface, 25 sx. - WOC 24 HRS - TAG

100' plug 1500' - 1600'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Laura Clepper TITLE Regulatory Analyst DATE 2-20-2004

Type or print name Laura Clepper E-mail address: lclepper@reimid.com Telephone No. 432 683-4816  
(This space for State use)

APPROVED BY [Signature] TITLE Wild Dog ID DATE FEB 24 2004  
Conditions of approval, if any: