District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Form C-141 Revised October 10, 2003

Release Notification and Corrective Action	
1KMW 1/09629398	OPERATOR Initial Report Final Report
Name of Company BOPCO, L.P. 260737 Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Contact Tony Savoie Telephone No. 432-556-8730
Facility Name Poker Lake Unit #158 Facility Type E&P API 30-015-31690	
Surface Owner Federal Mineral Own	er Federal Lease No.
LOCATION OF RELEASE	
	orth/South Line Feet from the East/West Line County
A 7 24S 30E	Eddy
Latitude_N 32.237400 Longitude W 103.914150	
NATURE OF RELEASE	
Type of Release: Produced water	Volume of Release: 230 bbls. Volume Recovered: 200 Bbls
Source of Release: Water transfer pump seal and piping failure.	Date and Hour of Occurrence Date and Hour of Discovery 3/21/11 time unkown 3/21/11 7:40 a.m.
Was Immediate Notice Given?	If YES, To Whom?
☐ Yes ☐ No ☐ Not Require	red Emergency NMOCD number
By Whom? Tony Savoie	Date and Hour 3/21/11 8:20 a.m.
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse. RECEIVED
If a Watercourse was Impacted, Describe Fully.*	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
<u>, </u>	APR 05 2011
	1
	NMOCD ARTESIA
Describe Cause of Problem and Remedial Action Taken.* A water transfer pump seal and bearings failed causing excessive vibration on the discharge	
piping of the pump. The power was shut off and valves were closed isolating the pump. The pump was replaced later the same day. Describe Area Affected and Cleanup Action Taken.*The entire area of the earthen containment was covered with produced, approximately 4500 sq.ft. The	
free standing water was removed and the saturated area around the tanks inside the containment was excavated and stockpiled on-site, remediation	
activities were under way under an approved remediation plan. The caliche pad area measuring approximately 2000 sq.ft. was affected by the misting of	
the produced water being sprayed into the air. The Site remediation for the produced water and spill will follow the NMOCD guidelines for leaks and spills.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health	
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other	
federal, state, or local laws and/or regulations.	OIL CONSERVATION DIVISION
Q^{2}	OIL CONSERVATION DIVISION
Signature: / Ong Sauce	Approved by District Supervisor;
Printed Name: Tony Savoie	Signed By M1/4 DESILLE
	.//. /
Title: Waste Mgmt.& Remediation Specialist	Approval Date: 4/6/// Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:
	Remediation per OCD Rules & Attached
Date: 4/4/11 Phone:432-556-8730 Attach Additional Sheets If Necessary	Guidelines. SUBMIT REMEDIATION
Attach Additional Sheets if Necessary	PROPOSAL NOT LATER THAN: 2RP. 7/7
	5/4/11