

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Oil Cons.
N.M. Div. Dist 2
1301 W. Grand Avenue
Artesia, NM 88210

Budget Bureau No. 1004-0135
Expires August 31, 1985

1. SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals.)		5. LEASE DESIGNATION AND SERIAL NO. LC-029419-A	
2. NAME OF OPERATOR The Wiser Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88241		7. UNIT AGREEMENT NAME Skelly Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 660' FEL Unit I		8. WELL NAME AND NO. 51	
14. PERMIT NO		12. COUNTY OR PARISH Eddy	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3851' DF		13. STATE NM	

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT * <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Plug and Abandon</u>	
(Other)		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12/10/03 MIRU Mayo Marrs Casing Pulling Inc. NU BOP. Tag CIBP@ 3122'. Spot 25 sks. cement @ 3122'. POH w/20 stands.

12/11/03 Tag @ 3027'. Circulate 10# mud. Spot 30 sks. @ 1670'-1570'. Spot 75 sks. @ 250' to surface. RD. Cut off WH & anchors. Level pit & cellar. Install dry hole marker. Move out. Well is P & A'd.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turner TITLE Production Tech II DATE January 7, 2004

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) ALEXIS C. SWOZDA TITLE PETROLEUM ENGINEER DATE FEB 23 2004

CONDITIONS OF APPROVAL, IF ANY:

*See Instruction On Reverse Side