

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	<input checked="" type="checkbox"/>	
FILE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
U.S.G.S.		
LAND OFFICE		
OPERATOR	<input checked="" type="checkbox"/>	

OIL CONSERVATION DEPARTMENT
P. O. BOX 2088
SANTA FE, NEW MEXICO 87505

RECEIVED BY
APR 04 1984
O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
LG 4352

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER- P&A

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
207 South 4th St., Artesia, NM 88210

4. Location of Well
UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 7S RANGE 24E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
Snakeweed SD State

9. Well No.
2

10. Field and Pool, or WHdcat
Pecos Slope Abo

15. Elevation (Show whether DF, RT, GR, etc.)
3753.1' GR

12. County
Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4050'. Reached TD 2:45 AM 3-24-84. Verbal permission obtained from Mike Williams, OCD, Artesia, NM on 3-24-84 to plug and abandon as follows:

- Plug #1: 35 sacks Class "C" Neat set 3500-3400'. PD 12:40 AM 3-25-84.
 - Plug #2: 35 sacks Class "C" Neat set 2790-2690'. PD 1:30 AM 3-25-84.
 - Plug #3: 35 sacks Class "C" Neat set 1350-1250'. PD 3:30 AM 3-25-84.
 - Plug #4: 35 sacks Class "C" Neat set 1000' in/out shoe. PD 4:00 AM 3-25-84.
 - Plug #5: 10 sacks Class "C" Neat set surface. Completed plugging 5:05 AM 3-25-84.
- Dry hole marker will be installed. Location will be cleaned and restored.

Post ID-2
4-13-84
P+H

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Supervisor DATE 4-3-84

APPROVED BY [Signature] TITLE Geologist DATE 12/7/89

CONDITIONS OF APPROVAL, IF ANY: