

C/SF

Form 9-231

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUBMIT TO OFFICE (Other side)

Budget Bureau No. 42-R1424

RECEIVED BY DEPARTMENT OF THE INTERIOR AUG 14 1985 O.C.D.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. ARTESIA, OFFICE

OIL WELL [ ] CAS WELL [ ] OTHER [ ]

2. NAME OF OPERATOR Yates Pet. Corp. NEWMONT OIL COMPANY

WTW - PNA

3. ADDRESS OF OPERATOR P. O. BOX 1305 ARTESIA, NEW MEXICO 88270

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface

2080' FNL & 560' FWL of Sec. 28

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3989' GLM

5. LEASE DESIGNATION AND SERIAL NO.

LC 063105

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

SQUARE LAKE FLOOD (FAST)

8. FARM OR LEASE NAME

SHELDON Fed.

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

SQUARE LAKE (G.SA)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 28-16S-31E NMPM

12. COUNTY OR PARISH

Eddy

18. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF [ ] FRACTURE TREAT [ ] SHOOT OR ACIDIZE [ ] REPAIR WELL [ ] (Other) [ ]

PULL OR ALTER CASING [ ] MULTIPLE COMPLETE [ ] ABANDON\* [ ] CHANGE PLANS [ ]

WATER SHUT-OFF [ ] FRACTURE TREATMENT [ ] SHOOTING OR ACIDIZING [ ] (Other) [ ]

REPAIRING WELL [ ] ALTERING CASING [ ] ABANDONMENT\* [X]

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The above well was plugged and abandon as follows:

6/25/82....Set 50 sack cement plug at 3436'.

6/26/82....Tagged bottom plug at 2580'. Perf base of salt at 1650'. Couldn't pump into perf. Spotted cement plug from 1550' to 1750' across perf. Perf top of salt 73 Squeezed w/41 sacks cement and shut-in.

6/29/82....Tag cement at 337'. Set dry hole marker at surface. 15' x surface plug.

Location ready for inspection

RECEIVED JAN 17 1983

OIL & GAS U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Area Manager

DATE 1/12/83

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE

DATE 8-13-85

CONDITIONS OF APPROVAL, IF ANY: